

FIRST RE-ESTABLISHMENT

GCDB 440200

Quarter corner common to Sections 27 and 34, Township 36 South, Range 4 West.

Found

- Snag BT to Southeast. Scribe marks damaged by fire.
- BT to Northwest blown down; stump hole plain; also scribed mark legible.

Set 3x4x30" pine stake.

Scribe 2" laurel C. S. B-T., which bears N66°05'W, 31.3 feet.

November 7, 1927
Boyden, Deputy County Surveyor
R. Smith and B. Kent, Chainmen

SEE NEXT PAGE FOR RE-ESTABLISHMENT SPECIAL CORNER

FIRST RE-ESTABLISHMENT
GCDB 440200

SPECIAL CORNER

Quarter corner common to Sections 27 and 34, Township 36 South, Range 4 West, W.M.

Found projecting 8 ins., the 1½ ins. diam. galvanized iron pipe, set by proportionate method, on Survey No. 2955 in 1965.

In the top of said pipe, set a 5/8 x 12 ins. rebar in cement, with yellow plastic cap marked:

"Jackson C.S."

Bearing trees marked in 1965 found:

- Madrone, 9 ins. diam. with healed single blaze, brs. Record: N4°E, 28.38 feet to center of tree at base.
- Madrone, 12 ins. diam., (leaning south) with axed into and rotted single face, brs. S19°E, 26.05 feet to center of tree at base. Record: 26.40 feet.

To perpetuate this location, marked a new tree "CS" "BT":

- Madrone, 10 ins. diam., brs. S5°E, 24.55 feet to center of tree at lower blaze.

Corner lies near top of Northeast (50%) slope, on ridge top c. Southeast and at South edge of old skid road, c. Easterly-Westerly.

July 16, 1987
R. Frost, Tech III
S. Beecher, Tech I

Edward McGinty
County Surveyor

V = 18°
P. -250