

FIRST RE-ESTABLISHMENT

GCDB 440700

North quarter corner of Section 3, Township 36 South, Range 4 West.

Found original bearing tree in Section 3, and the stump of witness tree in Section 34, T35S, R4W.

Set post for corner from which:

- An 8" white oak bears N8½°E., 16.6 feet.

A. T. Brown, Deputy County Surveyor
Harvey Ling, Chainman
George McMahon, present
January 21, 1914.

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 440700

Quarter corner on Township line of Section 3, Township 36 South, Range 4 West.

Found $\frac{3}{4}$ " pipe for corner and White Oak BT as reported by Deputy County Surveyor Brown - January 21, 1914.

From the $\frac{3}{4}$ " pipe for corner:

- The original BT, a 30" White Oak (intact), bears South $73\frac{1}{2}^{\circ}$ West, 51.5 feet.
- The White Oak BT marked by Surveyor Brown is in poor condition.

Scribed a 5" White Oak CS-BT which bears North 80° East, 41.1 feet.

March 26, 1938

C. Z. Boyden

C. I. Bourne

L. Pettegrew

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 440700

Quarter corner common to Section 34, Township 35 South, Range 4 West and Section 3, Township 36 South, Range 4 West.

Found the stumps of the Pine and White Oak reference trees established by the Jackson County Road Department survey crew in 1954. All other visual references have been dislodged or destroyed by road construction.

From said stumps, found the $\frac{3}{4}$ " iron pipe corner monument referred to by Deputy County Surveyor C. Z. Boyden on March 26, 1938 in the Second Re-establishment, 18" below the present surface of Earhart Road.

Replaced said $\frac{3}{4}$ " pipe monument with a 1"x36" galvanized iron pipe with bronze cap, stamped:

T35&36SR4W
¼ cor.
34 c.s.
¼S —
3
1965

With top 4" below the road surface for corner,

From which:

- Scribed a 10" Black Oak, "CS-BT" which bears South 30° East, 99.7 feet;
- Scribed an 8" Black Oak, "CS-BT" which bears South 33¾° West, 115.3 feet;

March 30, 1965
L. D. Pinkham, Deputy County Surveyor
Lloyd Hart

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 440700

Quarter corner common to Section 34, Township 35 South, Range 4 West and Section 3, Township 36 South, Range 4 West, W.M.

Found 9 ins. deep, in center of Earhart Road, unrecorded 2½ ins. brass cap set in concrete marked: T35S,R4W ¼ 34/3 T36S CS 1971. Found in "RPs for control point in danger by construction" page 7 and 18.

Set a 2½ ins. diam. brass cap set flush over found brass cap in concrete marked:

T35S R4W
34
¼S —
3
CS
T36S
1991

Bearing trees marked on third re-establishment in 1965 found with healed blazes and measured to center of tree at lower blaze:

- White Oak, 18 ins. diam., brs. S33°45'W, 115.20 feet. Record: 115.30 feet.
- White Oak, 17 ins. diam., brs. S30°E, 99.9 feet. Record: 99.7 feet.

Found ⅝ ins. iron pin set on survey No. 3214, in 1966, flush 3 feet North of E-W fence line, brs. N63°31'E, 67.29 feet.

New reference a Power Pole No. 1931, brs. N37°10'W, 30.04 feet to center.

October 15, 1991
T. Newcomb, Tech.
H. Durkee, Tech.

Verlyn Thomas
County Surveyor

P.-85