

FIRST RE-ESTABLISHMENT

GCDB 500100

Section corner common to Sections 34 and 35, Township 36 South, Range 4 West and Sections 2 and 3, Township 37 South, Range 4 West.

This corner was re-established by Deputy County Surveyor C. Z. Boyden on November 30, 1943 but was never made of record as the field notes for said re-establishment were incomplete.

Found the 5"x6"x7" stone with cross firmly in place as set for corner on said 1943 re-establishment.

Replaced said stone with a 1"x36" galvanized iron pipe set 35" in the ground with a 2½" bronze cap stamped:

T36-37SR4W
34 | 35
Sec. ——— Cor.
3 | 2
C.S.
1971

From which:

- The original Southwest bearing tree, (now an 18" White Oak in good condition with the upper face open and scribe visible) bears S15°W, 19.0 feet to the face of the upper blaze. (Original Record: 12" White Oak, S13°W, 19.14 feet);
- The stump hole of the original Pine bearing tree to the Northeast checks the government record. Found no evidence of the original bearing trees to the Northwest and Southeast.
- The bearing tree to the Southeast established on said 1943 re-establishment, now a 14" White Oak in good condition with healed faces bears S8½°E, 20.8 feet to the center. (1943 re-establishment: 12" White Oak scribed "CS-BT" bears S8½°E, distance omitted).
- The bearing tree to the Northeast established on said 1943 re-establishment, now a 27" broken off Pine snag with scribe visible bears N24°E, 32.1 feet to the face of the upper blaze (1943 re-establishment: 24" Pine scribed "CS-BT" bears N24°E, 32.1 feet).
- The bearing tree to the Northwest established on said 1943 re-establishment, now a 20" White Oak in poor condition with healed faces bears N11¼°W, 53.6 feet to the center (1943 re-establishment: 18" White Oak scribed "CS-BT" bears N11¼°W, 53.0 feet).

From said pipe corner, I establish a new bearing tree, to wit:

- Scribed a 6" Laurel "CS-BT" which bears N51¼°E, 10.2 feet to the face of the lower blaze.

March 5, 1971
Gary D. Kaiser,
Deputy County Surveyor

Otis Blankenship

SEE NEXT PAGE FOR ADDENDUM TO FIRST RE-ESTABLISHMENT

**ADDENDUM TO FIRST RE-ESTABLISHMENT
GCDB 500100**

Found said monument flush 1 ft. east of north-south course of old fence line.

Original bearing tree found now a 21 ins. diam. W. oak with open rotted upper blaze.

Bearing trees recorded in 1943 found;

- W. oak now 16 ins. diam. with healed double blaze
- W. oak still 20 ins. diam. with healed double blaze
- Pine snag

Bearing tree recorded on 1st re-establishment found with a healed double blaze, a Madrone now 9 ins. diam.

Corner lies approx. 900 ft. easterly from James Lehrmann Residence (1555 Birdseye Creek Road) to old fence intersection then approx 1400 ft. south along said fence.

May 5, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -107

V. - 14°50'