

## FIRST RE-ESTABLISHMENT

GCDB 500300

Section corner common to Sections 22, 23, 26 and 27, Township 36 South, Range 4 West.

Found original BTs to Southwest, Southeast, Northwest in place; also stump of BT to Northeast, BT to Southeast and Southwest check for distance. The BTs southwest and northwest chain 2.0 feet long.

Set 3x3" white oak post in mound of stone from which

- Scribe 22" yellow pine, C.S.-BT which bears  $N5^{\circ}15'E$ , 58.3 feet.

November 12, 1927  
Boyden, Deputy County Surveyor  
R. Smith, R. Kent, Scott and  
White, Chainmen

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 500300

Section corner common to Sections 22, 23, 26 and 27, Township 36 South, Range 4 West, W.M.

At the corner, found projecting 2 ins., the 2 ins. diam. galvanized iron pipe reported on Survey No. 1473, dated 1960. SEE also Jackson County "North River Road" Survey No. F-2-8, dated 1956. In the top of said pipe, set a 2½ ins. diam. bronze cap marked:

JACKSON COUNTY 1982  
T36S R4W  
22 | 23  
—+—  
27 | 26

- A burned out stump hole is found at record location of the Northeast bearing tree marked on First re-establishment, page 2, dated 1927 and noted on Survey No. 1473.
- Other recorded corner references were consumed by recent (1981) forest fire.

Set new references; 5/8 x 30 ins. rebars, 24 ins. in the ground with yellow plastic caps marked

"JACKSON C.S.":

- North, 12.4 feet.
- East, 6.15 feet.
- South, 9.00 feet.
- West, 24.5 feet.

The pump house for the state park sewer evaporation pond, brs. S43°W.

Corner lies on (55%) South slope.

October 19, 1982  
R. Frost  
R. Templin

Edward McGinty  
County Surveyor

V = 19½°  
P. -151

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT  
GCDB 500300**

Section corner common to Sections 22, 23, 26 and 27, Township 36 South, Range 4 West, W.M.

Found 2½ ins. diam. brass cap in 2 in. diam. iron pipe protruding 2 ins. above ground surface mkd:

JACKSON COUNTY  
1982  
T36S R4W  
22 | 23  
—+—  
27 | 26

Found 5/8 rebars, set on the Second Re-establishment dated 1982, with yellow plastic caps melted off.

- Protruding 3 ins. bears record East, 6.15 ft.
- Protruding 5 ins. bears record South, 9.00 ft.
- Protruding 5 ins. and leaning slightly North, bears record West, 24.5 ft.

The rebar set to the North is found out of the ground, reset pin now bears North 11.8 ft. (rebar leans slightly North).

Corner lies on (55%) South slope in recent burn (8-19-2011)

Search:

Lat. 42° 25' 07.60"  
Long. 123° 09' 01.28"

August 25, 2011  
S. Beecher

Kerry K. Bradshaw  
County Surveyor

P. - 7  
Series II Book I