

FIRST RE-ESTABLISHMENT

GCDB 500340

Quarter corner common to Sections 22 and 23, Township 36 South, Range 4 West, W.M.

At the corner, found flush in ring of stone, with top bent Northwesterly, the 3/4 in. diam. iron pipe set on Survey no. 4137, dated 1969. Alongside, set a 1 x 36 ins. galvanized iron pipe 21 ins. in the ground (with top directly over the center of undisturbed section of found pipe) with 2½ ins. diam. bronze cap marked:

JACKSON C.S.
T36S R4W
22 | 23
¼S

Bearing trees marked on Survey No. 1473, dated 1960 are now destroyed by recent (1981) forest fire, their remains found as follows:

- Partial Oak stump shell, about 15 ins. diam. and burnt, brs. Record: S12½°E, 36.5 feet.
- Burnt Madrone root crown, brs. Record: N43°W, 31.8 feet.

Original bearing trees are now gone.

Mk. new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- White Oak, 18 ins. diam., brs. S85½°E, 150.1 feet.
- The most Easterly Black Oak, 11 ins. diam., in clump of five Black Oaks, brs. N17½°W, 69.35 feet.

Corner lies on grassy South slope an estimated 100 feet South of top of ridge C. East-West.

June 8, 1982
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19½°
P. -78