

FIRST RE-ESTABLISHMENT

GCDB 500400

Section corner common to Sections 14, 15, 22 and 23, Township 36 South, Range 4 West, W.M.

At the corner, found flush, the 1½ ins. diam. iron pipe set on survey No. 1473, dated 1960. In the top of said pipe, in cement, set 2½ ins. diam. brass cap marked:

T36S R4W

15	14
22	23
C.S.	
1981	

A bearing tree marked on Survey No. 1473,

- A laurel, now 18 ins. diam., burned by recent fire, containing scribe marks in partially exposed upper face, brs. Record: S19°E, 39.10 feet to estimated lower face. Re-measured 39.75 feet to center of tree at lower blaze.

Mound stones around corner and marked a new tree "CS" "BT":

- Black Oak, 11 ins. diam., brs. S19°20'W, 49.90 feet to center of tree at lower blaze.

As remaining trees in vicinity of corner have been damaged or destroyed by fire, set 5/8 x 30 ins. rebars, flush with the surface of the ground with yellow plastic caps marked: "JACKSON C.S.":

- N60°E, 20.15 feet.
- S21°35'E, 37.44 feet.
- N21°35'W, 15.84 feet.

Corner lies about 50 feet East of draw C. Northwest and 1 feet Northeast of the wood post corner of South and West bearing fence lines.

October 12, 1981
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19°
P. -166