

PROPORTIONED CORNER

GCDB 540100

Quarter corner on Township line - Section 35, Township 36 South, Range 4 West, and Section 2, Township 37 South, Range 4 West.

No definite evidence of original corner.

Set a $\frac{3}{4}$ "x36" galvanized iron pipe on single proportion distance between the Section corners to East and West.

- A 36" White Oak scribed CS-BT bears South 81° West, 55.9 feet;
- Scribed a 16" White Oak CS-BT which bears North $27\frac{1}{2}^{\circ}$ West, 49.9 feet.

December 17, 1943

C. Z. Boyden

J. H. Cushman

PROPORTIONED CORNER – NO FIRST RE-ESTABLISHMENT

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 540100

Quarter corner common to Section 35, Township 36 South, Range 4 West and Section 2, Township 37 South, Range 4 West, W.M.

Found the $\frac{3}{4}$ " galvanized iron pipe 2" deep as set for corner by Deputy County Surveyor, C. Z. Boyden on December 17, 1943.

Set a 1"x36" galvanized iron pipe 34" in the ground with a 2 $\frac{1}{2}$ " bronze cap stamped:

T. 36-37S. R. 4 W.
35
 $\frac{1}{4}$ S — Cor.
2
C.S.
1971

For corner, from which:

- The First Re-establishment* bearing tree (now an 18" White oak with healed blazes) bears N27 $\frac{1}{2}$ °W, 50.3 feet to the center of the tree;
- The First Re-establishment* bearing tree (now a 30" White Oak with healed blazes) bears S81°W, 56.7 feet to the center of the tree;
- Found a $\frac{1}{2}$ " iron pipe, 2" deep in Footh Creek Road which bears East, 137.02 feet.

November 12, 1971
Gary Kaiser, Deputy County Surveyor
Lloyd Shreeve

NOTE: First Re-establishment refers to establishment of Proportioned Corner in 1943. (4/12/2016)