

FIRST RE-ESTABLISHMENT

GCDB 600340

Quarter corner common to Sections 23 and 24, Township 36 South, Range 4 West, W.M.

Found an unrecorded 2½ ins. diam. iron pipe projecting 8 ins. of which no record could be found. Set a 2½ ins. diam. brass cap at the top of found pipe marked:

T36S R4W
¼ S
23 | 24
CS
1994

Original bearing trees recorded by Ives and Hyde in 1854, found and measured to estimated faces:

- Stump hole with oak shell and burned double axed faces, brs. Record: S87°E, 13.86 feet.
- Stump hole brs. Record: S79°W, 44.88 feet.

New references taken:

- Set a 1x36 ins. diam. galvanized iron pipe 32 ins. in the ground brs. N81½°W, 7.70 feet.
- Found railroad rail 5 feet high, brs. North .93 feet.
- Set 5/8 x 24 ins. diam. rebar at record bearing and distance of original bearing trees. No cap on rebar.

Note: Could not occupy corner to take bearings from because of railroad rail.

June 29, 1994
T. Newcomb, Tech.
J. Burgess, Tech.

Verlyn Thomas
County Surveyor

V = 18°
P. -109