

## FIRST RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13 and 14, Township 36 South, Range 4 West, W.M.

By reference to the filed notes of the Surveyor General, I found the bearing trees as described.

I set a 1"x36" gas pipe as a monument to mark and perpetuate this corner.

From which:

- A 15" White Oak bears South 6° East, 55.0 feet. This is an original tree and is badly rotted.
- A 15" Black Oak bears North 5° West, 70.9 feet. This is an original bearing tree - the scribed area has been burned out.
- A 7" White Oak scribed "CS-BT" bears South 29¼° West, 31.2 feet (new).
- A 6" White Oak scribed "CS-BT" bears South 76°10' East, 37.3 feet.

October 5, 1938  
Lester E. Smith, Deputy C.S.  
C.A. Bourne, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13 and 14, Township 36 South, Range 4 West, W.M.

Found projecting 12 ins. and badly bent, the 1 ins. diam. iron pipe reported set on First re-establishment, page 9, in 1938. Replaced said pipe with and deposit it alongside of a 1 x 36 ins. galvanized iron pipe set 29 ins. in the ground. In the top of set pipe, set in concrete, a 2½ ins. diam. brass cap marked:

T36S R4W  
¼S  
14 | 13  
C.S.  
1986

Original bearing tree marked by Ives and Hyde in 1854 found:

- White Oak, now 19 ins. diam., with rotted faces, brs. Record: S6°E, 54.78 feet to estimated lower face.
- Black Oak, now 31 ins. diam. with rotted faces, brs. Record: N5°W, 70.62 feet to estimated upper face.

Bearing trees marked on First re-establishment found:

- White Oak, now 9 ins. diam. with double healed blazes, brs. S77°E, Record: 37.3 feet to estimated face. Record: S76°10'E. Re-measured 37.43 feet to center of tree at lower blaze.
- White Oak, now 12 ins. diam. with healed lower blaze, brs. S29½°W, Record: 31.2 feet to estimated lower face. Record: S79¼°W, Re-measured 31.48 feet to center of tree at lower blaze.

Corner lies in a small opening, on a 20% Northerly slope, an estimated 75 feet West of a small draw, course N30°W.

November 17, 1986  
D. Edwards  
T. Newcomb

Edward McGinty  
County Surveyor

V = 18½°  
P. -327

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

### THIRD RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13 and 14, Township 36 South, Range 4 West, W.M.

Found from the second re-establishment, dated 1986 a hole from where corner has been removed. At this position set a 1x30 ins. flanged galvanized iron pipe 27 ins. in the ground with attached 2½ ins. diam. brass cap marked:

JACKSON COUNTY SURVEYOR  
T36S R4W  
S¼  
14 | 13  
1993  
UNLAWFUL TO DISTURB

Original bearing trees recorded by Ives and Hyde in 1854 found with rotted faces:

- White Oak, 20 ins. diam., brs. Record: S6°E, 54.78 feet to estimated face. Re-measured 55.18 feet to center.
- Black Oak, 30 ins. diam., brs. Record: N5°W, 70.62 feet to estimated face. Re-measured 71.24 feet to center.

Bearing trees marked on first re-establishment, dated 1938 found with healed blazes:

- White Oak, 11 ins. diam., brs. Record: S29¼°W, 31.20 feet to estimated face. Re-measured 31.48 feet to center.
- White Oak, 7 ins. diam., brs. S76½°E, 37.30 feet to estimated face. Record: S76°10'E. Re-measured 37.43 feet to center.

Corner lies east about 80 feet from newly cleaned area for a building site.

February 25, 1993  
T. Newcomb, Tech.  
J. Burgess, Tech.

Verlyn Thomas  
County Surveyor

V = 17½°

P. -27