

FIRST RE-ESTABLISHMENT

GCDB 700500

Section corner common to Sections 12 and 13, Township 36 South, Range 4 West and Section 7 and 18, Township 36 South, Range 3 West, W.M.

Found a stone 3 x 24 x 26 ins., projecting 12 ins. with 2 notches to the North and 4 notches to the South. On the West face found incorrectly marked in large number " 12 6 13 7"

No record of this stone.

On Survey No. 2802 dated 1965, stone was replaced with a 1 in. diam. iron pipe, projecting 6 ins. with stone set on North side of pipe. In the top of found pipe set a 2½ ins. diam. brass cap marked:

T36S
12 | 7
R4W ——— R3W
13 | 18
CS
1992

Original bearing trees recorded by Ives and Hyde in 1854 found and measured to estimated face:

- Stump hole brs., record S57°W, 9.90 feet.
- Stump hole brs., record S35°E, 40.26 feet.

No remains of trees marked in 1965.

References: set a 5/8 x 24 ins. rebar with aluminum caps marked "Jackson County CS" projecting 6 ins.:

- S68°W, 6.84 feet. 5½ feet fence post set behind rebar.
- N25°W, 2.91 feet.
- N61½°E, 44.35 feet. 5½ feet fence post set behind rebar.
- Fence post is set at Southerly edge of cat road that slopes SW.
- S42°E, 4.23 feet.

Corner lies in area burned by fire between August 3 to August 6, 1992.

Set 5½ feet fence post on Easterly side of jeep road, course S68°W, N68°E. Posted location tag on fence post, corner brs. S48°E, 250 feet. ±

September 22, 1992
T. Newcomb, Tech.
J. Burgess

Verlyn Thomas
County Surveyor

V = 17½°
P.-94