

FIRST RE-ESTABLISHMENT

DLC39NW

GCDB 939050

Northwest corner of DLC 39, Township 36 South, Range 4 West.

At a point located on direct proportional distance with official Government record between the corner of Sections 15, 16, 21 and 22, and the most Westerly Southwest corner of DLC #39, which last two mentioned corners are established; I found a small mound of stone to mark the corner as per official government record. No evidence of the single original BT could be found.

Marked an "X" on the solid rock for corner (8" below the surface of ground),

From which:

- A cross marked near the highest point of solid rock outcrop 20'x4', cross being about 4' above the surface of the ground, bears South 15° West, 22.5 feet.
- An 8" Black Oak scribed CS-BT bears North 78¼° West, 78.5 feet;
- Set 1½'x18" pipe which bears North 101.0 feet.

August 7, 1936

C. Z. Boyden, Deputy County Surveyor

D. Clifford, Chainman

SECOND RE-ESTABLISHMENT

DLC39NW

GCDB 939050

Northwest Corner to DLC #39, Township 36 South, Range 4 West.

Found the cross on bedrock for corner, also the cross on top of highest point of rock outcrop which bears South 15° West, 22.45 feet, other references have been destroyed.

The following new references were established:

- A 14" Y. Pine scribed "CS" "BT" bears North $47\frac{1}{4}^\circ$ West, 54.9 feet;
- The center of a 12" Cedar bears South $35\frac{1}{4}^\circ$ West, 138.1 feet;
- The South corner of a one-story concrete block building bears North $8\frac{3}{4}^\circ$ East, 190.0 feet.

November 20, 1952
C. Z. Boyden
L. D. Pinkham & M.E. Boyden

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC39NW

GCDB 939050

Northwest corner of DLC #39, Township 36 South, Range 4 West.

During the execution of Recorded Survey No. 2430, the corner point, being a cross chiseled on bedrock, was referenced because a sizable fill was proposed over the corner area.

Found the reference points intact, from which set a 1"x24" galvanized iron pipe with bronze cap stamped:

T36S R4W
N.W. DLC
Cor. 39
C.S.
1965,

24" in the ground for corner,

From which:

- Found the cross at the Northeasterly end of a rock outcrop reported in the second re-establishment by Deputy County Surveyor, C. Z. Boyden on November 20, 1952, which bears South 15° West, 22.45 feet;
- A lead with tack at the Southeasterly end of a concrete sidewalk along the Northeasterly side of Gail's Market pumice block building bears North 25¾° East, 141.70 feet;

The most-Westerly corner of said Market building bears North 9° West, 91.95 feet.

Var. 20° East
January 6, 1965
F.A. Roberts
G. Kaiser

Approved By:
Mark E. Boyden
County Surveyor

FOURTH RE-ESTABLISHMENT

DLC39NW

GCDB 939050

Northwest corner to Donation Land Claim No. 39, Township 36 South, Range 4 West, W.M.

Found 18 ins. deep, the brass cap described on Third re-establishment, page 18, in 1965. Directly over found brass cap, set in concrete, 6 ins. below the surface of the ground, a 2½ ins. brass cap marked:

T36S R4W
DLC
N.W.
39
C.S.
1983

From which: references recorded on Third re-establishment found:

- A found lead plug in the Southeast corner of concrete walkway in front of concrete block (market) building, brs. Record: N25°45'E, 141.70 feet.
- A chiseled cross in the highest point of rock outcrop, brs. Record: S15°W, 22.45 feet.

Note: The building corner noted as "N9°W, 91.95 feet.", in 1965, is no longer visible due to (concrete block) addition to building.

Set new reference;

- Rebar, 5/8 x 30 ins. with yellow plastic cap marked "JACKSON County C.S." set flush with the top of and on the Northerly side of concrete curb, brs. N85°29'E, 13.27 feet.

Corner lies at the South edge of asphalt parking area and about 19 feet, S77°E of power pole No. R-5280.

December 8, 1983
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19°
P. -163

SEE NEXT PAGE FOR FIFTH RE-ESTABLISHMENT

FIFTH RE-ESTABLISHMENT

DLC39NW

GCDB 939050

V = 16°

Northwest corner to Donation Land Claim No. 39, Township 36 South, Range 4 West, W.M.

Found the 2½ ins. diam. brass cap set on the Third Re-establishment, dated 1965, marked;

T36S R4W

NW | DLC
COR | 39
CS
1965.

18 ins. deep

The brass cap set on the Fourth Re-establishment, dated 1983, is not found.

Directly over the found brass cap set a 1 in.x 18 ins. galvanized iron pipe in cement with 2½ diam. brass cap marked; T36SR4W, cemented in top flush with ground.

DLC

• | NW
| 39
2012

References recorded in 1983 found;

- Chiseled 'X' on the highest point of a rock outcrop bears record S15°W, 22.45ft.
- Yellow plastic cap marked 'JACKSON C.S.', located at the backside of curbing at North side of paved area bears N85°30'E, 13.27 ft. Record bearing N85°29'E.

Set new references, Mag Nails with washers marked 'C.S.'

- Near northwest corner of square storm drain bears S69°E, 20.93 ft.
- 7 ft. East of power pole #R5280 bears N59°W, 14.62 ft.

Corner is located at the westerly edge of paved area South of motel and West of market.

September 29, 2012
S. Beecher

Scott D. Fein
Deputy County Surveyor

P. - 4
Series II Book I