

FIRST RE-ESTABLISHMENT

DLC39WSW

GCDB 939040

Most Westerly Southwest corner of DLC #39. Township 36 South, Range 4 West.

Found stone to mark corner; also all three original BTs, which check official record.

Set a 1½x36" galvanized pipe 28" in the ground for corner at the exact location of the above mentioned stone; corner falls in the bottom of a small draw,

- The original BT, a 28" White Oak (intact) bears S35°W, 45.6 feet.
- The original BT, a 22" Black Oak plainly scribed bears South 51° East, 103.0 feet.
- The original BT to NE in poor condition.
- Mark an "X" in top of 12" concrete retaining wall for spring near the S.E. end which bears N45°05'W, 85.2 feet.

August 6, 1936

C. Z. Boyden, Deputy County Surveyor

Dave Clifford, Chainman

Fred Younger, Chainman

SECOND RE-ESTABLISHMENT

DLC39WSW

GCDB 939040

West Southwest corner to Donation Land Claim No. 39, Township 36 South, Range 4 West, W.M.

At the corner, found projecting 2 ins., the 1½ ins. diam. iron pipe set on First re-establishment, page 7, in 1936. In the top of said pipe, in cement, set a 2½ ins. diam. brass cap marked:

T36S R4W
WSW
39
DLC
C.S.
1982

The single remaining original bearing tree marked by S. Truax in 1855,

- A Black Oak, now 27 ins. diam. with healed blazes, brs. S51°E, 104.8 feet to center. Record: 102.96 feet. **Note:** This tree erroneously noted to be "White Oak" on First re-establishment.

The cross marked on the retaining wall in 1936 is not found due to the recent construction of a spring house on the old foundation.

- Chisel a new cross on the Southeast concrete corner of the spring house footing. Said cross brs. N44°33'W, 84.55 feet.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- White Oak, 6 ins. diam., brs. N7°50'E, 60.00 feet.
- Ponderosa Pine, 8 ins. diam., brs. S67°37'W, 58.18 feet.

Corner lies in small spring branch c. N45°E.

June 24, 1982
E. McGinty
R. Frost

Edward McGinty
County Surveyor

V = 19½°
P. -92