

FIRST RE-ESTABLISHMENT

DLC40NW

GCDB 940060

Northwest corner DLC #40, Township 36 South, Range 4 West, W.M.

Found mound of stone to mark the corner. Original BT to Northwest plainly scribed; also stump holes of BT to Southeast and Southwest which checks the mound of stone found to mark the corner.

Set a 1½ x 36" galvanized pipe in said mound of stone 20" in the ground for corner

From which:

- The original BT a 12" White Oak bears North $82\frac{1}{2}^{\circ}$ West, 41.6 feet;
- Scribe a 14" Black Oak CS-BT which bears South 43° West, 49.8 feet;
- A 18" White Oak scribed CS-BT bears North $72\frac{3}{4}^{\circ}$ East, 155.9 feet.

September 20, 1935
C. Z. Boyden, Deputy County Surveyor
O. H. Tice, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC40NW

GCDB 940060

Northwest corner to Donation Land Claim 40, Township 36 South, Range 4 West, W.M.

Found flush with the surface of the ground, the 1½ ins. diam. iron pipe, set for the corner on First re-establishment, page 6, in 1935. In the top of found pipe, set in cement, a 2½ ins. diam. brass cap marked:

T36S R4W
1982

NW
DLC C.S.
40

- An original bearing tree, a White Oak, now 15 ins. diam. with burned and/or axed into faces, brs. Record: N82½°W, 41.6 feet to center.
- A bearing tree marked on First re-establishment, a Black Oak, now 22 ins. diam. with healed blazes, brs. Record: S43°W, 49.8 feet to estimated face. Re-measured 50.38 feet to center of tree.

Mound stones around corner and marked a new tree "CS" "BT":

- Black Oak, 6 ins. diam., brs. S71°E, 31.93 feet to center of tree at lower blaze.

Corner lies 45 feet North of spring branch, C. S40°E.

February 2, 1982
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19°
P. -14