

## FIRST RE-ESTABLISHMENT

DLC40SSE

GCDB 940040

South Southeast corner of DLC #40, Township 36 South, Range 4 West.

Found 1½"x31" galvanized iron pipe set 27" in the ground for corner;

Also found original BT to Northwest and the remains of original BTs to Northeast and Southwest which corner as found agrees with the official Government records.

From the above mentioned 1½"x31" galvanized iron pipe corner

- The original BT a 30" Black Oak plainly scribed, bears North 36½° West, 88.5 feet.
- Scribe a 12" Black Oak CS-BT which bears North 79° East, 38.6 feet;
- Scribe a 16" Black Oak CS-BT which bears South 87¼° West, 46.3 feet.

August 22, 1940

C. Z. Boyden

C. I. Bourne

A. H. Smith

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

**SECOND RE-ESTABLISHMENT**

**DLC40SSE**

**GCDB 940040**

South Southeast corner of Donation Land Claim No. 40, located in Section 21, Township 36 South, Range 4 West, W.M.

Found flush, the 1 1/2 ins. diam. iron pipe reported set on first re-establishment, page 11, in 1940. In the top of said pipe, set in concrete, a 2 1/2 ins. diam. brass cap marked:

T36S R4W  
DLC  
SSE 40  
C.S.  
1987

No trace of original bearing trees found

Bearing tree marked on said first re-establishment found:

- Black Oak, now 14 ins. diam. with double healed blazes, brs. Record: N79°E, 39.2 feet to center of tree at lower blaze. Record distance; 38.6 feet.

Scribe new trees "CS" "BT" and measure to center of tree at lower blaze:

- Black Oak, 19 ins. diam., brs. S1½°W, 50.86 feet.
- Douglas Fir, 5 ins. diam., brs. N50¾°W, 14.55 feet.

Corner lies in small trees on 45% North slope, 30 feet North of the middle of a gravel driveway, course N70°W - S70°E.

August 24, 1987  
D. Edwards, Tech  
S. Beecher, Tech

Edward McGinty  
County Surveyor

V = 18½°  
P. -309