

FIRST RE-ESTABLISHMENT

DLC41SSW

GCDB 941070

South Southwest corner of DLC #41, Township 36 South, Range 4 West.

Set 1½"x36" galvanized pipe for corner.

The original BTs to Northwest to Northeast.

Scribe a 28" Black Oak CS-BT which bears North 7°30' East, 47.8 feet.

February 17, 1928
C. Z. Boyden, Deputy County Surveyor
B. Seaman, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC41SSW

GCDB 941070

South Southwest corner of Donation Land Claim No. 41, Township 36 South, Range 4 West.

Found a 1½" iron pipe, exposed 8" in a mound of stone, for corner; also the remains of the original bearing tree to the Northeast and the stump hole of the Southwest tree.

- The original bearing tree, a 19" Black oak, bears North 61½° West, 15.1 feet to the face of the upper blaze.
- The tree marked on the first re-establishment is dead and down but the stump hole checks the record.
- A 14" Red Fir marked on Recorded Survey No. 2955 bears south 38½° West, 17.3 feet.
- An 11" Red Fir marked on the same survey bears North 32° East, 17.9 feet.
- Scribed a 7" Pine CS-BT which bears South 56° East, 9.0 feet to the face of the upper blaze.

October 18, 1967

F. A. Roberts

J. Huston

Approved By:

L. D. Pinkham

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC41SSW

GCDB 941070

South Southwest corner to Donation Land Claim No. 41, located in Section 34, Township 36 South, Range 4 West, W.M.

Found the 1½ ins. diam. galvanized iron pipe set on the first re-establishment, dated 1928, protruding 8 ins. above ground. Set a 2½ ins. diam. brass cap marked:

T36S R4W
DLC
SW
41
CS
1989

In cement in the top of found pipe from which:

The original bearing tree marked by S. Truax in 1856:

- Black Oak 18 ins. diam., dead with exposed and rotted upper face, brs. Second Re-establishment Record: N61½°W, 15.4 feet to the center of tree at base.

Second re-establishment references, dated 1967, found:

- Fir stump 11 ins. diam., 4 feet high with scribe marks visible on beetle ravaged face, brs. Record: N32°E, 18.15 feet to center of stump.
- Ponderosa Pine, 13 ins. diam., with healed blazes, brs. S55°E, 9.25 feet to center of tree at lower blaze. Record bearing; S56°E.
- Fir stump, 14 ins. diam., 4 feet high with rotted face, brs. S39°W, 17.8 feet to center of stump. Record bearing; S38½°W.

Mk new trees "CS" "BT" and measure to the center of tree at lower blaze:

- Ponderosa Pine 11 ins. diam., brs. N16¾°E, 59.3 feet.
- Ponderosa Pine 11 ins. diam., brs. S90°W, 20.9 feet.
- A power pole R993 brs. N56°E, 42.0 feet.

Corner lies at the rear and between residences 1396 and 1414 Birdseye Creek Road

August 22, 1989
S. Beecher, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 18½°
P. -175