

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 30 AND 31 ONLY
GCDB 100200**

Standard corner Sections 30 and 31, Township 38 South, Range 1 West, W.M.

Found the corner stone with the 5 and 1 notches scribed on the edges lying on the ground but not in place.

Also found the NE BT with old axe marks, the SE Laurel BT with old blazes burned out, the old SW BT, a Black Oak with scribe destroyed by Surveyor Gibbs in 1908 now a 14" Black Oak with old blaze

From which evidence:

- Set a 2" x 36" galvanized iron pipe 22" in the ground for corner from which a 10" Black Oak scribed CS-BT bears S87°E, 46.4 feet.
- The original BT now a 40" fir with old blaze bears N50°E, 31.7 feet.

October 21, 1953
C. Z. Boyden
L. D. Pinkham
M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 30 AND 31 ONLY
GCDB 100200**

Standard corner Sections 30 and 31, Township 38 South, Range 1 West, W.M.

Found at the corner, the 2-inch diameter iron pipe, projecting 10 inches in mound of stone, set on First re-establishment in 1953. In the top of said pipe, set a 3-inch diameter brass cap marked:

T38S
R2W R1W
| 30
|
| 31
| C.S.
| 1981

An original bearing tree recorded by Ives and Hyde in 1854,

- Now a Douglas Fir snag, 46-inch diameter, with exposed and rotted lower face, bears Record: N50°E, 31.68 feet to said face.

Marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Black Oak, 6-inch diameter, bears N70°E, 35.30 feet.
- Douglas Fir, 6-inch diameter, bears S3°E, 28.14 feet.

The (brass cap) closing corner of Sections 25 and 36, T38S, R2W, bears S0°18'W, 69.9 feet. Original Record: W.N. Gibb 1909; South 69.96 feet.

SEE ALSO Survey No. 1702 dated 1961.

Corner lies on Southeast slope about 60 feet West of skid road c. Northeast and about 870 feet West of location marker on 12-inch diameter Ash alongside road and edge of creek.

April 15, 1981
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19°
P. -63