

FIRST RE-ESTABLISHMENT

GCDB 140300

Quarter corner common to Sections 19 and 30, Township 38 South, Range 1 West, W.M.

Found projecting 8 inches, the 1½-inch diameter iron pipe set on Survey No. 2116.

Replace said pipe with and deposit it alongside of a 1 x 36-inch Galvanized iron pipe, 30 inches in the ground, with a 2½-inch diameter brass cap marked:

T38S R1W
19
¼S —
30
C.S.
1986

Original bearing trees marked by Ives and Hyde in 1854 found:

- Fir stump, 30-inch diameter with partial scribe mark visible in opened lower face, bears Record: N60°E, 7.26 feet to said face.
- Fir stump, 30-inch diameter with scribe marks including "4s" and "BT" visible in exposed upper and lower faces, bears Record: S70°W, 17.16 feet (slope distance) to said lower face.

Bearing trees marked on Survey NO. 2116 found and Re-measured to center of tree at root crown:

- Cedar, now 12-inch diameter with single healed blaze, bears S38½°E, 61.15 feet. Record: S39¼°E, 60.72 feet.
- Madrone, now 15-inch diameter with deteriorating bark scribe visible, bears N37½°W, 20.57 feet. Record: N41°W, 20.46 feet.

Scribe new tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Douglas Fir, 10-inch diameter bears N18¾°E, 19.14 feet.

Corner lies in a moderately brushy area, on a 75% Northeasterly slope an estimated 100 feet Southerly from the bottom of a small draw.

October 30, 1986
D. Edwards
T. Newcomb

Edward McGinty
County Surveyor

V = 20°
P. -298