

FIRST RE-ESTABLISHMENT

GCDB 200200

Section corner common to Sections 29, 30, 31 and 32, Township 38 South, Range 1 West, W.M.

From the following evidence, and attempting to re-monument the corner reportedly set from original evidence on Survey No. 2116 in 1963, set a 1x36-inch Galvanized iron pipe 32 inches in the ground.

In the top of said pipe, set in concrete, a 2½-inch diameter brass cap marked:

T38S	R1W
30	29
31	32
C.S.	
1988	

Original bearing tree reported found on Survey No. 2116 is no longer evident.

- A 1¼-inch diameter iron pipe is found alongside new monument.

Bearing trees marked on said Survey No. 2116 found with single healed blaze and measured to center of tree at root crown:

- Ponderosa Pine, now 26-inch diameter, bears Record: N60½°E, 60.06 feet.
- White Oak, now 10-inch diameter, bears S20¾°W, 39.96 feet. Record: S20°W, 40.92 feet.
- White Oak, now 9-inch diameter, bears N50¼°W, 15.84 feet. Record: N54½°W.

Very old rails for East-West fence lies South, an estimated 15 feet. The corner post to fences bearing North and West bears N57°W, 11.0 feet.

Corner lies in a small opening, on an eroding creek bank, 6.0 feet West of stream center.

March 2, 1988
D. Edwards, Tech.
T. Newcomb, Tech.

Edward McGinty
County Surveyor

V = 18½°
P. -73