

FIRST RE-ESTABLISHMENT

GCDB 240200

Quarter corner common to Sections 29 and 32, Township 38 South, Range 1 West, W.M.

Found no evidence of the original corner or bearing trees.

Set a 1" x 36" galvanized iron pipe 34" in the ground with a 2½" bronze cap stamped:

T38S R1W
29
¼S — Cor.
32
C.S.
1970

In a mound of rock to perpetuate the corner location established by Surveyor Gottlieb Elksnat (circa 1905).

From which:

- The bearing tree established by Elksnat (Now a 24" Douglas Fir, plainly scribed "¼S" with approximately 65 growth rings over the blaze) bears N14¾°E, 9.9 feet to the face of the upper blaze (Elksnat Record: 12" Fir bears N14¾°E, 9.9 feet.)
- The corner monument set by Surveyor Marvin C. Ramsey on Recorded Survey No. 2116, a 1½" galvanized iron pipe, exposed 5" in a mound of rock, with tag marked RS 404, bears N56¾°E, 7.91 feet.
- The bearing tree established on said recorded survey No. 2116(now a 20" Douglas Fir stump plainly scribed) bears S47¼°E, 29.2 feet to the center.

Marked the following new trees:

- A 14" Douglas Fir, scribed "CS-BT" bears N75¼°E, 35.5 feet to the face of the lower blaze.
- A 9" Douglas Fir, scribed "CS-BT" bears S41¾°E, 22.9 feet to the face of the lower blaze.

March 10, 1970
Otis Blankenship
Dan Phillips

Approved by:
M. E. Boyden,
County Surveyor