

SPECIAL CORNER

FIRST RE-ESTABLISHMENT

GCDB 300500

Section corner common to Sections 8, 9, 16 and 17, Township 38 South, Range 1 West, W.M.

Found the 1½-inch diameter iron pipe set by proportionate method on Survey No. 1142, dated 1958, 14 inches below surface of gravel drive, with a 5⁄8-inch rebar and yellow plastic cap marked "Friar LS961" protruding 8 inches above the center of pipe.

Set a 1x12 inches iron pipe, directly over the found pipe and rebar, with a 2½-inch diameter brass cap marked:

T38S R1W	
8	9
17	16
C.S.	
1988	

Cemented in top of pipe.

References from Survey No. 1142 found:

- ½-inch diameter iron pipe 18 inches below the ground surface, old county road PI, bears S89°27'40"E, 327.96 feet. Record: 328.0. (Set a 5/8x18-inch rebar with yellow plastic cap marked "Jackson C.S." directly over found pipe).
- Northwest corner of residence No. 2211 Houston Road bears S22°01'10"E, 146.03 feet. Record: 146.3. New siding on house.

To perpetuate this position take or set the following references:

- 5⁄8-inch rebar with yellow plastic cap marked "Friar LS961, set on Survey No. 10331, bears S89°34'50"E, 329.99 feet. Record: 330.0 feet.
- 5⁄8 x24-inch rebar with yellow plastic cap marked "Jackson C.S." flush, 2 feet East of Power Pole No. D12003, bears N01°12'40"W, 11.52 feet.
- 5⁄8 x 24-inch rebar with yellow plastic cap marked "Jackson C.S." flush, 1 foot North of southerly fence along driveway, bears S78°39'20"W, 40.60 feet.

Corner lies approximately 200 feet West of Houston Road in the South track of gravel driveway to residence 2245 Houston Road and 10 feet South of Power Pole No. D12003 with location tag.

May 23, 1988
S. Beecher, Tech.
R. Frost, Tech.

Edward McGinty
County Surveyor

P. -204