

FIRST RE-ESTABLISHMENT

GCDB 340300

Quarter corner common to Sections 21 and 28, Township 38 South, Range 1 West, W.M. $V = 21^\circ$

Found $\frac{5}{8}$ -inch diameter re-steel rod, projecting 1 in., set by L. E. Ager in 1967. Reference: R.S. #3486.

Over said bar I drove a 1 x 36-inch G.I. pipe 28 inches in the ground with a $2\frac{1}{2}$ -inch bronze disc marked:

T38S R1W
21
 $\frac{1}{4}$ S —
28
Jackson County 1974

At record location of original BTs (Ives and Hyde, 1854) no evidence other than stump holes found.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- A White Oak, 7-inch diameter, bears $S19^\circ 40'E$, 54.13 feet.
- A White Oak, 5-inch diameter, bears $N70^\circ 39'W$, 17.06 feet.
- The corner of a North-South and East-West fence line bears $N65^\circ W$, 1.5 feet.
- A found $\frac{5}{8}$ -inch diameter, re-steel rod, (aerial marker) set flush with the ground, bears $S65^\circ 33'E$, 109.74 feet.

June 17, 1974
B. Malotte
R. Frost

Approved by:
Edward McGinty,
County Surveyor

NOTE:

Found brass cap missing from 1-inch diameter iron pipe, 6 inches deep.

Set new brass cap $2\frac{1}{2}$ -inch diameter marked:

T38S R1W
21
 $\frac{1}{4}$ S —
28
Jackson County 1998

In top of found pipe.

Corner lies at the NW corner of property. Address is 6318 Adams Road.

April 17, 1998, T. Newcomb