

## FIRST RE-ESTABLISHMENT

GCDB 400200

Section corner common to Sections 27, 28, 33 and 34, Township 38 South, Range 1 West, W.M.

Found the witness tree in Section 28 destroyed and the stump of the tree in Section 33. The field notes call for a White Oak tree in Section 27, but instead at the proper bearing and distance found a Black Oak with the witness marks thereon. The witness tree in Section 34 is intact.

The above-mentioned Black Oak is decayed and sour-sapped. Set two new trees properly scribed with section, township and range numbers, as follows:

- A 4" White Oak bears N29½°E, 26.6 feet.
- An 8" White Oak bears S6½°W, 44.6 feet.
- No tree near in Section 28.

March 24, 1914  
A. T. Brown,  
Deputy County Surveyor

H. Ling, Chainman  
P. Murphy, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 400200

Section corner common to sections 28, 27, 33 and 34, Township 38 South, Range 1 West, W.M.

Found the original Northeast BT with the BT scribe intact, also the remains of roots for the Southwest and Southeast original BTs.

Also found the re-established Northeast BT with scribe legible which was established by County Surveyor A.T. Brown in the year 1914, also remains of the re-established Southwest BT.

From which evidence: Set a 2" x 31" galvanized iron pipe 28" in the ground for corner which fall alongside the remains of an old corner fence post.

From which:

- Brown's BT, now a 12" White Oak plainly scribed, bears  $N29\frac{1}{2}^{\circ}E$ , 26.6 feet.
- Scribe an 8" White Oak with two old blazes CS-BT, which bears  $S89\frac{1}{4}^{\circ}W$ , 49.7 feet.
- Scribe an 8" Black Oak CS-BT which bears  $S79^{\circ}E$ , 89.0 feet, no tree near in the Northwest quadrant.

November 13, 1953

C. Z. Boyden

L. D. Pinkham

Tom Furnas

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

### THIRD RE-ESTABLISHMENT

GCDB 400200

Section corner common to Sections 27, 28, 33 and 34, Township 38 South, Range 1 West, W.M.  
 $V = 20\frac{1}{2}^\circ$

Found, at the corner the 2-inch diameter G.I. pipe projecting 2 inches as set on Second Re-establishment in 1953.

Set in said pipe and secure with cement, a 2½-inch diameter brass cap marked:

T38S	R1W
28	27
33	34
CS	
1980	

Found the bearing tree marked on above re-establishment:

- White Oak, dead and down, 12-inch diameter with healed double blazes, the stump hole of which bears  $S89^\circ 15'W$ , 44.6 feet. Record  $S89\frac{1}{4}^\circ W$ , 44.6 feet.
- A bearing tree marked on 1914 First re-establishment, A White Oak, now 13-inch diameter with partial scribe marks in upper face bears  $N29^\circ 30'E$ , 26.37 feet. Record:  $N29\frac{1}{2}^\circ E$ , 26.6 feet.
- The single original bearing tree, marked by Ives and Hyde in 1854, Black Oak, 16 inches diameter with axed and rotted faces bears  $N45^\circ 45'E$ , 38.28 feet. Record:  $N42^\circ E$ , 38.28 feet.

New references:

- $\frac{5}{8}$  x 30-inch rebar driven flush with yellow plastic cap marked "JACKSON C.S.":
- $N26^\circ 50'E$ , 14.86 feet.
- $N45^\circ W$ , 16.34 feet.

Corner lies  $S52^\circ W$ , 2.0 feet from corner of North-South and East-West bearing wood post fence corner.

August 7, 1980  
R. Frost  
D. Danielsen  
J. Gallegos

Approved by: Edward McGinty  
County Surveyor

P. -169