

## FIRST RE-ESTABLISHMENT

GCDB 500100

Sections 34 & 35, Township 38 South, Range 1 West and Sections 2 & 3, Township 39 South, Range 1 West.

Found the 2"x 36" galvanized iron pipe set by myself in 1946 at which time I found an old cedar stake for corner and the remains of trees to the Northwest and Southwest which agree with the official government record, from the said 2"x36" pipe for corner.

- A 1 1/8" x 17" iron pin bears North 20.0 feet, scribe a 6" black oak CS-BT (on one blaze) which bears North 64° West, 50.4 feet;
- Scribe a 12" pine CS-BT which bears South 6° West, 172.2 feet.
- The center of an 8" telephone pole bears South 22½° East 51.5 feet.
- A 1½" galvanized iron pipe at the S.S.E. corner DLC #67 bears South 89½° East, 352.4 feet.

March 16, 1954

C. Z. Boyden

L. D. Pinkham

M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 500100

Found, 10 inches below the surface of the road, the 3-inch diameter brass cap marked:

JACKSON COUNTY  
T38S & 39SR1W  
34 | 35  
—|—  
3 | 2  
1972  
CONTROL MON.

As recorded in "Cor's. Re-monumented for Triangulation Nets" "Fall 1972" book on file.

References recorded on First Re-establishment in 1954 found as follows:

- 1 1/8-inch diameter, iron pin, flush with the surface of the ground, located 18 inches South of East-West fence line, bears  $N0^{\circ}10'W$ , 20.00 feet. Record: North, 20.0 feet
- Ponderosa Pine, 18-inch diameter with healed blazes, bears  $S5^{\circ}50'W$ , 172.54 feet to center of tree. Record:  $S6^{\circ}W$ , 172.2 feet.
- Black Oak, 15-inch diameter with healed single blaze, bears record,  $N64^{\circ}W$ , 50.4 feet to estimated face. Re-measured 50.65 feet to center of tree.

I set new references, 5x30-inch rebars, flush with the surface of the ground, with yellow plastic caps marked: "JACKSON C.S." bears:

- $S40^{\circ}41'E$ , 31.75 feet.
- $S28^{\circ}17'W$ , 38.74 feet.

Basis of bearing: South Southeast corner Donation Land Claim No. 67,  $S89\frac{1}{2}^{\circ}E$ .

Corner lies at intersection of Yank Gulch and Holton Roads.

December 7, 1979  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor

SEE NEXT PAGE FOR ADDENDUM TO SECOND RE-ESTABLISHMENT

**ADDENDUM**  
**GCDB 500100**

**Note:** Found 12 inches deep the 2½-inch diameter brass cap set on Second Re-establishment, dated 1979.

Over found monument set flush with pavement in concrete a 2½-inch diameter brass cap marked:

T38SR1W  
34 | 35  
—|—  
3 | 2  
T39S  
CS  
1993

May 17, 1993  
T. Newcomb, Tech  
J. Burgess, Tech

**SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT**

### THIRD RE-ESTABLISHMENT


#### GCDB 500100

Section Corner common to sections 34 and 35, Township 38 South, Range 1 West, and Sections 2 and 3, Township 39 South, Range 1 West, W.M.

Found the 2½-inch diameter brass cap set in 1993 apparently having been broken out of pavement reset in road tar and turned 180°.

Dug down 12 inches and found the 1972 Control Monument described on the Second Re-Establishment, dated 1979.

Directly over the found monument, set in concrete, a 1x10-inch Galvanized iron pipe with 2½-inch diameter brass cap marked:



Basis of Bearing: Witness Corner to south southeast corner of Donation Land Claim No. 67, Township 38 South, Range 1 West, bears S89°30'E 332.71 feet.

References found or set on the Second Re-establishment:

- 5/8-inch diameter rebar with yellow plastic cap marked 'JACKSON CS' flush with ground, bears S28°15'10"W, 38.72 feet. Record S28°17'W, 38.74 feet.
- Ponderosa Pine 20-inch diameter, with healed blazes, bears S05°49'W, 172.42 feet to the center of tree at lower blaze. Record S06°W, 172.20 feet.
- Black Oak 19-inch diameter, with healed blazes, bears N64°24'W, 50.40 feet to the center of tree at lower blaze. Record N64°W, 50.65 feet.

New Reference;

- Found red plastic cap marked 'BAROTT LS2332' flush with ground set on Survey No.16600, dated 2000, bears S42°24'03"E, 33.80 feet. Record S41°57'23"E, 33.78 feet.

Corner is located at the intersection of Yank Gulch Road and Holton Road

August 16, 2000  
T. Newcomb

Roger Roberts  
County Surveyor

P. -33