

FIRST RE-ESTABLISHMENT

GCDB 540500

Quarter corner to Sections 11 and 14, Township 38 South, Range 1 West.

Found the stumps of both original Black Oak witness trees (with scribe marks legible in the Southwest stump), which stumps fit in proper relation to the original Government Record.

From which evidence:

- Set a 1"x 36" galvanized iron pipe in the bottom of a small irrigation ditch for corner.

From which I scribe CS-BT on the following new trees:

- A 10" White Oak which bears S11°E, 5.4 feet;
- A 10" White Oak which bears S49½°E, 118.0 feet;
- A 12" White oak which bears S19°W, 71.5 feet.

December 13, 1956

Mark E. Boyden

K. D. Weaver

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 540500

Quarter corner common to Sections 11 and 14, Township 38 South, Range 1 West, W.M.

Found at the corner, 5 inches deep, in concrete, a brass cap 3-inch diameter marked:

T38S R1W
11
¼S — Cor.
14
C.S.
1972

(No record of this monument found)

Bearing trees noted on First re-establishment in 1956 found:

- Northwest branch, 14-inch diameter of triple White Oak with healed double blaze, bears S11°E, 6.3 feet to center of tree at lower blaze, (record 5.4 feet.)
- White Oak, 12-inch diameter with healed double blaze, bears S49½°E, 118.45 feet to center of tree at lower blaze, (record 118.0 feet.)
- Most Northerly branch, 14-inch diameter, of double White Oak with healed blazes, bears S18°50'W, 71.90 feet to center of tree at lower blaze, (record S19°W, 71.5 feet.)

Set new references: Rebars, 5/8-inch diameter, 30 inches long, with yellow plastic caps marked: "JACKSON C.S." flush on East-West fence line.

- S62°45'E, 6.92 feet.
- S60°54'W, 6.53 feet.

Corner lies 3.5 feet North of East-West fence line and an estimated 200 feet West of S.W. corner of orchard.

April 14, 1981
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19½°
P. -61