

FIRST RE-ESTABLISHMENT

GCDB 540600

Quarter corner common to sections 2 and 11, Township 38 South, Range 1 West, W.M.

No evidence of corner found, set by single proportionate measurement during the course of survey number 20414. Set a 2 ins. diam. by 30 ins. long flanged GIP, with a 3 ins. diam. brass cap MKD:

JACKSON COUNTY SURVEYOR
T38S R1W
 $\frac{1}{4}$ S $\frac{2}{11}$
2009
UNLAWFUL TO DISTURB

From which the following references were taken:

- $\frac{5}{8}$ -ins. diam. by 24 ins. long rebar with $1\frac{1}{2}$ ins. diam. aluminum cap MKD: Jackson County Surveyor Set flush at the NE corner of an asphalt strip in an E-W granite road. Brs: S11°04'19"W, 102.68 ft.
- 17 ins. diam. W. Oak, upper blaze "CS", lower blaze "BT" Brs: S69°08'W, 65.86 ft.
- 8 ins. diam. W. Oak, upper blaze "CS", lower blaze "BT" Brs: N41°51'E, 119.52 ft.
- 11 ins. diam. B. Oak, upper blaze "CS", lower blaze "BT" Brs: S56°34'E, 165.95 ft.

Corner lies approximately 100 ft. N. of E-W granite road in an area of scatter oaks.
See Survey No. 20414

March 20, 2009

S. Fein

Kerry K. Bradshaw
County Surveyor

Series II, Book I
P. 31-32