

FIRST RE-ESTABLISHMENT

GCDB 700200

Section corner common to sections 25, 36, 30, 31 in Township 38 South Range 1 West and Range 1 East, was established during the course of survey number 4457, performed by PLS 759.

Monument set on said survey has been destroyed by an irrigation pond. Utilizing control from said survey this section corner has been re-established and position checked very well to the two bearing trees taken on S/N 4457.

Due to the existing irrigation pond it is not possible to set the section corner at its position. Therefore reference monuments were set and referenced as follows.

RM NO. 1: 2 ins. x 30 ins. flanged GIP with a 3 ins. diam brass cap, set flush, MKD:

T38S R1E
RM
NO. 1
2008

- From this monument the section corner position brs. $S74^{\circ}21'54''W$, 62.87 ft.
- Search coordinate NAD 83 (1991) N 213171.0/ E 4309924.1

References taken to RM NO.1:

- $\frac{5}{8}$ -ins. x 24 ins. rebar with a $1\frac{1}{2}$ ins. diam. Aluminum cap brs. $S15^{\circ}46'34''E$, 46.54 ft. Lies at NE corner of metal hay shed.
- $\frac{5}{8}$ -ins. X 24 ins. rebar with a $1\frac{1}{2}$ ins. diam. Aluminum cap brs. $N74^{\circ}16'58''W$, 42.08 ft. Lies at SE corner of westerly horse corral



Aluminum cap

RM NO. 2: 2 ins. x 30 ins. flanged GIP with a 3 ins. diam brass cap, set flush, lies at NE corner of westerly horse corral, 2 ft. south of fence corner. MKD:

T38S R1E
RM
NO. 2
2008

- Brs. $N15^{\circ}16'48''W$, 70.42 ft.
- From this monument the section corner position brs. $S26^{\circ}19'07''W$, 94.69 ft.
- Search coordinate NAD 83 (1991) N 213239.4 E 4309907.4

References taken to RM NO. 2:

- $\frac{5}{8}$ -ins. x 24 ins. rebar with a $1\frac{1}{2}$ ins. diam. Aluminum cap brs. $S15^{\circ}28'39''E$, 116.96 ft. Lies at NE corner of metal hay shed.
- $\frac{5}{8}$ -ins. x 24 ins. rebar with a $1\frac{1}{2}$ ins. diam. Aluminum cap brs. $S21^{\circ}13'05''W$, 60.64 ft. Lies at SE corner of westerly horse corral.
- **RM NO. 1**, as described above: brs. $S15^{\circ}16'48''E$, 70.42

FIRST RE-ESTABLISHMENT CONTINUED ON NEXT PAGE

FIRST RE-ESTABLISHMENT (Continued)

GCDB 700200

References to the section corner only:

- Found 14 ins. diam (record: 10 ins.) black oak with healed blazes, brs. N20°09'13"E, 140.33 ft. Record (S/N 4457): N20°08'E, 140.33 ft.
- Found 9 ins. diam (record: 6 ins.) white oak with healed blazes, brs. N54°34'51"E, 157.61 ft. Record (S/N 4457) N54°38'E, 157.61 ft.

Field work completed between 4/15/08 and 4/17/08

See Job File 2008-02

May 29, 2008

S. Fein

S. Beecher

Roger Roberts

County Surveyor

Series II, Book I

P. 9-10 Field Notes