

## FIRST RE-ESTABLISHMENT

DLC46ELL

GCDB 846110

Northeast corner of DLC #48, Township 38 South, Range 1 West, Also the inside "L" corner of DLC #46, Township 38 South, Range 1 West.

Found a 6" x 8" x ? basalt stone firmly set with top 4" above the ground level for corner. This stone corner was found and accepted as the true corner by the engineering firm of Osgood and Cummings in 1910.

Chiseled a cross on top at the Northwest corner of the South concrete wall of a check gate dam which bears N20¼°W, 17.40 feet:

- The center of Copco Power Pole No. D6637 bears North 57½° East, 44.1 feet;
- A 5/8" x 30" iron pin bears westerly on the North boundary of DLC #48, 182.15 feet.

February 9, 1959

M. E. Boyden

L. D. Pinkham

**NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

DLC46ELL

GCDB 846110

Northeast corner to DLC No. 48, identical with the inside "L" of DLC No. 46, located in Section 8, Township 38 South, Range 1 West, W.M.

Found 10 inches deep, the base of the stone recorded on First Re-establishment in 1959, with broken off section containing chiseled cross found alongside.

Replaced the above with a 2½-inch diameter brass cap marked:

T38S R1W  
DLC  
NE  
48  
C.S.  
1984

Set in concrete.

References recorded in 1959 found as follows:

- The center of "Copco" power pole, No. 6637, bears Record: N57½°E, 44.1 feet.
- Chiseled cross atop the Northwest corner of the South wall of concrete irrigation dam, bears Record: N20¼°W, 17.40 feet.

Set new references; 5/8 x 30-inch rebars, flush, with yellow plastic cap marked "Jackson County C.S."

- N57°30'E, 16.43 feet.
- N36°41'W, 9.68 feet located 12 feet South of the center of irrigation ditch.

The Southeast corner of Wood frame house, an estimated 300 feet distant, bears S77°16'W.

June 15, 1984  
R. Frost  
E. McGinty

Edward McGinty  
County Surveyor

V = 19°  
P. -85