

FIRST RE-ESTABLISHMENT

SPECIAL CORNER

DLC46NW

GCDB 200632

Northwest corner of Donation Land Claim No. 46, Township 38 South, Range 1 West, W.M.

Found 2 inches deep, the ¾-inch diameter rebar, set for the corner on Survey No. 8422, dated 1980.

Directly over said rebar set a 1x36-inch Galvanized iron pipe, flush, with 2½-inch diameter brass cap marked:

T38S R1W
DLC
┌NW
│46
└C.S.
1989

From which:

- A 1-inch diameter galvanized iron pipe, found flush and leaning South-Southwest bears S54½°W, 0.29 feet to top of pipe. Reference Jackson County Project File No 89.3.

Set new references: 5/8 x 24-inch diameter rebars set flush with yellow plastic cap(s) marked "Jackson C.S." bears:

- N0°13'E, 15.77 feet, located 4 feet South of Power pole D7941.
- N89°43'W, 32.69 feet, located 2 feet East of North-South (board) fence line.

The (brass cap) Northeast corner of DLC 47 bears N0°00'13"E, 210.08 feet. Record: (Survey No. 8422) 210.07 feet.

See Also Jackson County Project File 89-3.

February 7, 1989
R. Frost, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

P. 51-52