

FIRST RE-ESTABLISHMENT

DLC47NE

GCDB 200637

Northeast corner of DLC #47, Township 38 South, Range 1 West (Also Southerly L DLC #50)

Found stone 12" in diameter by ?, 36" below the surface of the ground, being the recognized corner for over 30 years.

From which:

- A + chiseled in top of a 6" corner, etc.
- Head wall near the westerly end bears $S5\frac{1}{4}^{\circ}W$, 57.96 feet.
- A 1"x ? iron pipe at the NW corner DLC #46 bears southerly 210.28 feet,
- A + chiseled near the SW corner of a concrete head gate bears $N18\frac{3}{4}^{\circ}W$, 11.02 feet to the north corner of a concrete foundation of a wood frame residence bears $S24\frac{1}{4}^{\circ}E$, 218.4 feet.
- The approximate center of the county road bears South 24 feet.

February 19, 1940

C. Z. Boyden

C. I. Bourne

A. H. Smith

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC47NE

GCDB 200637

Northeast DLC No. 47, Township 38 South, Range 1 West, W.M. (Also the Southerly "L" DLC #50)

Found, at the corner, 12 inches deep, a 1½ x 27-inch iron pipe.

I replaced the above with a 1 x 28-inch G.I. pipe, with 2½-inch diameter bronze disc marked:

JACKSON COUNTY 1980
T38S R1W
DLC

N.E.
47

Set 10 inches below the surface of the ground in concrete.

The above noted 1½-inch diameter pipe is found directly over the flat (unmarked) stone, 36 inches deep, recorded as the corner on First Re-establishment in 1940, and below a ¾ x 10-inch G.I. pipe of unknown origin.

References recorded on First Re-establishment found:

- The Northwest corner of concrete foundation of residence 243 South Stage Road, bears S24°37'E, 218.21 feet. Record: S24¼°E, 218.4 feet.
- Chiseled cross in West end of concrete headwall bears S5°12'W, 57.96 feet. Record: S5¼°W, 57.96 feet.
- G.I. pipe, 1-inch diameter found flush, leaning Westerly noted on First re-establishment as the Northwest corner of DLC #46, bears South, 210.28 feet. Record: Southerly, 210.28 feet.

I set new references:

- ⅝ x 24-inch rebar, flush, with yellow plastic cap marked: "Jackson C.S." located at the West end of concrete headwall, bears S6°35'W, 57.74 feet.
- ⅝ x 30-inch rebar, flush, with yellow plastic cap marked: "Jackson C.S." located at the Southwest corner of concrete headwall bears N21°44'W, 10.89 feet.
- A found 1¼-inch diameter iron pipe projecting 8 inches bears S36°29'W, 57.25 feet.

Corner lies about 10 feet West of middle of gravel road, course; North-South and approximately 29 feet North of center of South Stage Road.

June 24, 1980

R. Frost

D. Danielsen

Witnesses: Paul Lewis and Cliff Birk

Approved by: Edward McGinty

County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT SPECIAL CORNER
DLC47NE
GCDB 200637

Northeast corner of Donation Land Claim No. 47, identical with the Southerly "L" corner of Donation Land Claim No. 50, Township 38 South, Range 1 West, W.M.

Monument set on Second Re-establishment in 1980 is now gone, possibly removed during installation of telephone equipment in 1981.

inches deep, with 2½-inch diameter brass cap marked:

T38S R1W
DLC
NE 47
C.S.
1989

From which:

- Chiseled cross in the west end of concrete headwall, bears S5°19'W, 57.96 feet. Record: S5°12'W.
- A 5/8-inch diameter rebar, found projecting 1 inch, with yellow plastic cap marked "Jackson C.S.", at the west end of concrete headwall, bears S6°41'W, 57.74 feet. Record: S6°35'W.
- A 1¼-inch diameter iron pipe found projecting 8 inches, bears S36°36'W, 57.25 feet. Record: S36°29'W.
- A 5/8-inch diameter rebar found projecting 1 inch with yellow plastic cap marked: "Jackson C.S." at the southwest corner of a concrete irrigation box, bears N21°39'W, 10.89 feet. Record: bearing N21°44'W.
- The (brass cap) Northwest corner of DLC 46, bears S0°00'13"W, 210.08 feet. Record (survey No. 8422) 210.07 feet.

Visibility to the house foundation reported in 1980 is now obstructed.

Take a new reference:

- A 3/4-inch diameter pin, found 12 inches deep, noted on 1936 Jackson County road survey (map J-4-10) bears Record: S51°04'E (basis bg.) 335.40 feet.

See also; Jackson County Project File 89-3.

February 7, 1989
R. Frost, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

P. -50

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT SPECIAL CORNER
DLC47NE
GCDB 200637

Northeast Corner of Donation Land Claim No. 47, identical with the Southerly 'L' Corner of Donation Land Claim No. 50, Township 38 South, Range 1 West, W.M.

Found an unrecorded 2½-inch diameter brass cap flush with pavement and marked:

T38S R1W
DLC
C.S.
1994
NE 47

From which:

- Found 1¼-inch diameter iron pipe projecting 1 inch, bears Third Re-establishment, dated 1989. Record: S36°36'W, 57.25 feet.

The brass capped Northwest Corner of Donation Land Claim No. 46 can no longer be seen due to trees. All other previous re-establishment references are not found.

New references:

- Found .38 Special shell casing at the Southwest corner of a 4-foot x 4-foot concrete irrigation box, bears N08°42'40"W, 24.67 feet.
- Found projecting 1 inch a yellow plastic cap marked "JACKSON County Road & Parks SVC.," bears S00°23'12"E, 56.76 feet. Located at the Northeast edge of concrete curbing for irrigation ditch.
- Marked a '+' on the South side of manhole rim, bears S85°30'55"E, 56.08 feet.

April 20, 2000
T. Newcomb

Roger Roberts
County Surveyor

P.-13