

FIRST RE-ESTABLISHMENT

DLC50SE

GCDB 850160

Southeast corner to DLC #50, Township 38 South, Range 1 West.

Found remains of old cedar stake for corner, set a 1½"x 36" galvanized iron pipe on the North boundary of DLC #46 at the location of the stake the recognized Southeast corner of DLC #50.

From which:

- A 1"x 20" iron pin bears N72°15'E, 98.1 feet, the Northeast corner DLC #46 (a stone with cross in top) bears S89°55'E, 93.45 feet;
- Nail in Southeast base of a power pole bears S21½°W, 28.25 feet.

February 20, 1940

C. Z. Boyden

C. I. Bourne

A. H. Smith

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC50SE

GCDB 850160

Southeast corner DLC No. 50, Township 38 South, Range 1 West, W.M.

Found 18 inches below the surface of South Stage Road, the iron pipe, 1½-inch diameter, set for the corner of First Re-establishment, in 1940.

Directly over said pipe, flush with the surface of the road, set brass cap in concrete marked:

T38S R1W
S.E.
_____ } 50 C.S.
DLC
1981

The (brass cap Northeast corner of DLC 46, bears S89°51'E, 93.45 feet. Record (1940): S89°55'E.

Set new references; rebars, 5/8-inch diameter, 30 inches long, flush with the ground, with yellow plastic caps marked "Jackson C.S." bears:

- N4920'E, 41.68 feet, located at west end of rail fence c. East-West.
- N26°38'W, 29.12 feet, located 1 foot South of multiple (4) branch White Oak.

February 19, 1981
R. Frost
R. Templin

Edward McGinty
County Surveyor

P. -30