

FIRST RE-ESTABLISHMENT

DLC57SSE

GCDB 857120

South Southeast corner of DLC #57, Township 38 South, Range 1 West, W.M.

Found a 3/8" iron pipe at the base of an old anchor post, with fences running Northerly and Westerly therefrom. This pipe was used for control of the East boundary of DLC #57 on Recorded Survey No. 661.

Set a 1" x 36" galvanized iron pipe (with 3/8" iron pipe inside) with a bronze cap stamped:

T38S R1W
SSE
Cor.
57
CS
1972

32" in the ground for corner.

From which:

- Set a 5/8" x 30" iron pin N0°18'E, 30.00 feet.
- Set a 5/8" x 30" iron pin N89°42'W, 30.00 feet.

True bearings used.

December 30, 1963
L. D. Pinkham
Lloyd Hart

Approved by:
M. E. Boyden,
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT


SECOND RE-ESTABLISHMENT

DLC57SSE

GCDB 857120

South Southeast corner of Donation Land Claim #57, Township 38 South, Range 1 West, W.M.

Found 4 inches deep in concrete, 3-inch diameter brass cap marked:



Mound stones around corner and measure references reported on First Re-establishment, page 37, in 1963, 5/8-inch diameter smooth iron pins found flush:

- N0°18'E (Basis of Bearing), 30.00 feet. Record: 30.00 feet.
- N89°42'06"W, 29.98 feet. Record: N89°42'W, 30.00 feet.

Take new references:

- White Oak, multiple branched, 11-inch diameter, scribed "CS" "BT", bears N12°54'E, to center of tree at lower blaze, 12.61 feet to center of most easterly branch at upper face.
- Rebar 5/8 x 24 inches with Jackson County metal cap, set flush, along the east side of (new) pear tree.

Corner lies on East side of 6 x 8 inches wood post, corner of north and west bg. fence lines.

***SEE JOB FILE 95-1**

March 16, 1995
R. Frost, Tech.
T. Newcomb, Tech.

Roger Roberts
County Surveyor

P. -24