

## FIRST RE-ESTABLISHMENT

DLC59SW

GCDB 859120

Southwest corner DLC #59, Township 38 South, Range 1 West, W.M. (Also Exterior "L" DLC #60)

Found a  $\frac{3}{4}$ " iron pipe to mark the corner. Also found the  $1\frac{1}{2}$ " pipe at the Southeast corner DLC #58, which bears South 172.96 feet (Government record 172.92 feet.)

For an additional corner monument set a  $1\frac{1}{2}$ " x 34" galvanized iron pipe 38" in the ground at the exact location of the said  $\frac{3}{4}$ " pipe.

From which:

- The most Easterly 1" iron bolt in the concrete base of the Westerly signal Block #4353 bears N42 $\frac{1}{2}$ °W, 410.2 feet.
- The center of the S.P. County Railroad main line track bears N47 $\frac{1}{2}$ °E, 9.0 feet.
- The most Southwesterly pear tree bears N47 $\frac{1}{4}$ °E, 57.7 feet.

January 4, 1954

C. Z. Boyden

L. D. Pinkham

M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

DLC59SW

GCDB 859120

Southwest corner of DLC #59, also the exterior "L" of DLC #60, Township 38 South, Range 1 West, W.M. Section 23.

Found the 1½-inch diameter iron pipe marking the Southwest corner of DLC #59, per the First Re-establishment by C. Z. Boyden, in 1954.

From which the remaining reference from the First Re-establishment are:

- The most Easterly 1-inch bolt on the concrete base of the westerly signal block (No. 4353) of the Southern Pacific Railroad bears N42°36'W, 410.17 feet. Record N42½°W, 410.2 feet.
- The Octagon Gun barrel marking the Southeast corner of DLC No.58 bears South 172.88 feet. Record 172.96 feet.

I set a 5/8 x 30-inch re-bar with yellow plastic cap marked "Jackson C.S." bears S74°38'30"E, 80.52 feet, one foot Northwesterly of a power pole, flush with ground.

Corner lies S47½°W, 9 feet from the center of the Southern Pacific Railroad main line and N42½°W, 87 feet from the centerline of Colver Road at the Railroad crossing.

Basis of Bearing: First Re-establishment bearing to the Southeast corner of DLC No. 58.

June 25, 1979  
Jerry Swanson

Approved by: Edward McGinty  
County Surveyor

**SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT**

**THIRD RE-ESTABLISHMENT**

**DLC59SW**

**GCDB 859120**

Southwest corner to Donation Land Claim No. 59, also being the exterior "L" of Donation Land Claim No. 60, located in Section 23, Township 38 South, Range 1 West, W.M.

Found the 1½ inches iron pipe set on First Re-establishment in 1954, 4 inches deep and badly mushroomed.

Set inside of said pipe a 1x22-inch Galvanized iron pipe flush with ground with a 2½-inch diameter brass cap marked:

T38S R1W  
DLC  
SW  
59  
CS  
1989

Reference set on Second Re-establishment in 1979 found:

- 5/8-inch rebar with yellow plastic cap set flush, bears S74°38'E, 80.55 feet. Record: 80.52 feet.
- Rebar is 1 foot Northwest from power pole.

Set new references:

- 5/8 x 24-inch rebar with yellow plastic cap marked "Jackson CS":
- N78°32` E, 51.57 feet. This is located on easterly edge of R.R. right of way and 8 feet west of irrigation ditch at edge of orchard.
- N78°43'W, 28.58 feet. This is located at the top of bank on westerly side of R.R. right of way and 8 feet East of barb wire fence.

Brass cap marked for the Southeast corner of Donation Land Claim No. 58, bears South, 172.88 feet.

Corner lies 6.5 feet S60°W, from westerly rail of railroad tracks and 87 feet N42°30'W, from center line of Colver Road at rail crossing.

November 7, 1989  
T. Newcomb, Tech.  
S. Beecher, Tech.

Verlyn Thomas  
County Surveyor

P. -219