

FIRST RE-ESTABLISHMENT

DLC60EXL

GCDB 859120

Southwest corner DLC #59, Township 38 South, Range 1 West, W.M. (Also Exterior "L" DLC #60)

Found a $\frac{3}{4}$ " iron pipe to mark the corner. Also found the $1\frac{1}{2}$ " pipe at the Southeast corner DLC #58, which bears South 172.96 feet (Government record 172.92 feet.)

For an additional corner monument set a $1\frac{1}{2}$ " x 34" galvanized iron pipe 38" in the ground at the exact location of the said $\frac{3}{4}$ " pipe.

From which:

- The most Easterly 1" iron bolt in the concrete base of the Westerly signal Block #4353 bears N42 $\frac{1}{2}$ °W, 410.2 feet.
- The center of the S.P. County Railroad main line track bears N47 $\frac{1}{2}$ °E, 9.0 feet.
- The most Southwesterly pear tree bears N47 $\frac{1}{4}$ °E, 57.7 feet.

January 4, 1954

C. Z. Boyden

L. D. Pinkham

M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC60EXL

GCDB 859120

Southwest corner of DLC #59, also the exterior "L" of DLC #60, Township 38 South, Range 1 West, W.M. Section 23.

Found the 1½-inch diameter iron pipe marking the Southwest corner of DLC #59, per the First Re-establishment by C. Z. Boyden, in 1954.

From which the remaining reference from the First Re-establishment are:

- The most Easterly 1-inch bolt on the concrete base of the westerly signal block (No. 4353) of the Southern Pacific Railroad bears N42°36'W, 410.17 feet. Record N42½°W, 410.2 feet.
- The Octagon Gun barrel marking the Southeast corner of DLC No.58 bears South 172.88 feet. Record 172.96 feet.

I set a 5/8 x 30-inch re-bar with yellow plastic cap marked "Jackson C.S." bears S74°38'30"E, 80.52 feet, one foot Northwesterly of a power pole, flush with ground.

Corner lies S47½°W, 9 feet from the center of the Southern Pacific Railroad main line and N42½°W, 87 feet from the centerline of Colver Road at the Railroad crossing.

Basis of Bearing: First Re-establishment bearing to the Southeast corner of DLC No. 58.

June 25, 1979
Jerry Swanson

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC60EXL

GCDB 859120

Southwest corner to Donation Land Claim No. 59, also being the exterior "L" of Donation Land Claim No. 60, located in Section 23, Township 38 South, Range 1 West, W.M.

Found the 1½ inches iron pipe set on First Re-establishment in 1954, 4 inches deep and badly mushroomed.

Set inside of said pipe a 1x22-inch Galvanized iron pipe flush with ground with a 2½-inch diameter brass cap marked:

T38S R1W
DLC
SW
59
CS
1989

Reference set on Second Re-establishment in 1979 found:

- 5/8-inch rebar with yellow plastic cap set flush, bears S74°38'E, 80.55 feet. Record: 80.52 feet.
- Rebar is 1 foot Northwest from power pole.

Set new references:

- 5/8 x 24-inch rebar with yellow plastic cap marked "Jackson CS":
- N78°32` E, 51.57 feet. This is located on easterly edge of R.R. right of way and 8 feet west of irrigation ditch at edge of orchard.
- N78°43'W, 28.58 feet. This is located at the top of bank on westerly side of R.R. right of way and 8 feet East of barb wire fence.

Brass cap marked for the Southeast corner of Donation Land Claim No. 58, bears South, 172.88 feet.

Corner lies 6.5 feet S60°W, from westerly rail of railroad tracks and 87 feet N42°30'W, from center line of Colver Road at rail crossing.

November 7, 1989
T. Newcomb, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

P. -219