

FIRST RE-ESTABLISHMENT

DLC60SW


GCDB 860120

Southwest corner to Donation Land Claim No. 60 also being the "L" corner to Donation Land Claim No. 62, located in Section 22, Township 38 South, Range 1 West, W.M.

Found projecting 10 inches with top bent 6 inches northerly, an "L" shaped 1x48-inch iron pipe. This pipe is old, rusty and the "X" described on Survey No. 3066 is no longer discernible.

To perpetuate this location, replace said pipe with and deposit it alongside a 1x72 inches (two sections) galvanized iron pipe, set 65 inches in the ground with a 2½-inch diameter bronze cap marked:

JACKSON COUNTY 1984



References reported on Survey No. 3066, found as follows:

- Chiseled cross atop the Southeast wall of concrete irrigation structure, bears N57°18'E, 9.70 feet. Record: N57°W.
- Iron pin, 5/8-inch diameter, found 10 inches deep, 0.10 feet South of East-West fence line bears Record: N83°30'E, 18.70 feet.
- 60d spike found on the West side of (wood) post corner of North and East bearing fence line bears Record: N7°W, 3.46 feet.

Set new reference:

- Rebar, 5/8 x 30-inch, set 3 inches deep, with yellow plastic cap marked: "JACKSON C.S." located 1 foot west of North-South fence line bears N3°58'W, 12.33 feet.

Corner lies at the Northwest edge of small irrigation ditch c. East and Southerly.

October 29, 1984

R. Frost

E. McGinty

Edward McGinty

County Surveyor

V = 18½°

P. -124

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT
DLC60SW
GCDB 860120

SEE SURVEY NO. 19094.