

FIRST RE-ESTABLISHMENT

DLC61NW

GCDB 857130

Northwest corner DLC #61 - Also the inside Ell corner DLC #57. Township 38 South, Range 1 West.

No definite evidence of the original corner.

From the South-Southeast corner DLC #57 ran Northerly through a stone monument on the East boundary of DLC #57, said stone being the center line of the Colver Road and produced the said DLC line Northerly 1244.0 feet distance as shown by survey records (which distance is called 1241.5 feet by an early survey record) set a 1½" x 36" galvanized iron pipe 36" in the ground for corner.

From which:

- Set a ⅝" x 30" iron pin on the West line of said DLC #61 at a distance of 30 feet.
- Also set a ⅝" x 30" iron pin on the North line of DLC #61 at a distance of 40 feet.
- Scribe a 10" wild cherry CS-BT (on one blaze) which bears South 79¾° East, 8.4 feet.

September 4, 1954

C. Z. Boyden

M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC61NW

GCDB 857130

Northwest corner of DLC No. 61, located in Section 22, Township 38 South, Range 1 West, W.M.
(Also ELL Corner of DLC #57)

Found, 1½ x 36-inch iron pipe bent and 2 inches deep, as established by C. Z. Boyden on First Re-establishment in 1954. I removed, straightened, and placed it back in original position from reference points.

Inside of which I drive a 1 x 36-inch G.I. pipe with 2½-inch diameter bronze disc marked:

JACKSON COUNTY 1979

ELL 57

DLC

NW
61

17 inches into found pipe and 6 inches below ground.

Reference points as recorded on above re-establishment I find as follows:

- 5/8-inch diameter steel re-bar 6 inches deep, bears record, East, 40.00 feet.
- 5/8-inch diameter steel re-bar 2 inches deep bears S00°04'E, 30.00 feet. Record: South, 30.00 feet.
- Placed a 6 feet metal fence post 1 foot Southeasterly from corner projecting 4 feet.

Corner lies on Southerly side of farm road and on Northwesterly corner of pear orchard.

July 24, 1979
J. Gallegos
J. Swanson

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC61NW

GCDB 857130

Northwest corner of Donation Land Claim No. 61, located in Section 22, Township 38 South, Range 1 West, W.M.

Found at the corner position and 6 ins. deep, the 2½ ins. diam. brass cap set on 2nd Reestablishment in 1979, marked:

JACKSON COUNTY 1979
ELL 57

DLC NW 61

References recorded on 2nd Re-establishment, 5/8 in. diam. rebar with yellow plastic caps marked:

JACKSON COUNTY

●
C.S.

Found re-measured:

- Found flush brs. S89°41'18"E, 40.00 ft. record; East.
- Found 2 ins. deep brs. S0°09'28"W, 29.99 ft. record; S0°04'E, 30.00 ft.

Establish new references:

- 2 ins. diam x 5 ft. high iron post, from which fences br. north, south and east, brs. N48°29'08" W, 1.93 feet
- Northwest corner of Donation Land Claim No. 57, brs. N72°49'47"W, 2040.91 ft,
- NNE corner of Donation Land Claim No. 62, brs. N89°26'35"E, 2000.25 ft.

Corner lies at NW corner of Pear Orchard and approximately 2 ft. southeasterly of fence corner.

May 15, 2003

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. - 80