

FIRST RE-ESTABLISHMENT

DLC64SE

GCDB 864110

Southeast corner of DLC #64 (Also NE DLC #65), Township 38 South, Range 1 West.

Found $\frac{3}{4}$ " x 30" galvanized iron pipe for corner.

From which:

- The remains of the yellow pine bearing tree to the SW checks the official government record.
- A $1\frac{1}{2}$ " x 36" galvanized iron pipe 8" below the surface of the ground for the corner at the exact location of the above mentioned $\frac{3}{4}$ " pipe.

From which:

- The center of the circle in the figure 9 in 1917 cast in the top of the easterly concrete head wall of Culvert No. 434 bears N59°54'W, 173.6 feet.
- The center of a 24" x 24" x 60" stone masonry gate post bears S0°02'E, 434.6 feet.

June 4, 1928
C. Z. Boyden,
Deputy County Surveyor

Clyde Esterbrock

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC64SE

GCDB 864110

Southeast corner of DLC #64 and the Northeast corner of DLC No. 65, Township 38 South, Range 1 West, W.M.

From the references set prior to building construction, I set a 1 x 23-inch G.I. pipe, in cond., with brass cap marked:

Jackson County 1977	
T38S R1W	
SE 64	
-----	DLC
NE 65	

From which:

- A lead plug with tack set in the concrete floor of a storage building, in the most westerly of two doorways and 3½ feet East of the SW corner of the building, bears N27°W, 68.28 feet. Bearing by hand compass.
- A lead plug with tack set in the concrete floor of a storage building, in the most Westerly of two doorways and 4.2 feet East of the SW corner of the building, bears N68°E, 12.26 feet, bearing by hand compass. This lead plug is 0.5 feet lower in elevation than the brass cap.

The references set prior to building construction are as follows:

- ¾ x 37-inch steel pin, set flush in the crushed rock fill of the railroad bed, about 6 feet East of the East rail, bears S26°W, 74.41 feet.
- ⅝ x 16-inch steel pin, set flush in said crushed rock fill, about 8 feet East of the East rail, bears N77°01'W, 97.33 feet.
- ⅝ x 16-inch steel pin, set flush at NW edge of asphalt surface of Rapp Road, bears S34°09'E, 196.59 feet. Using the hand compass bearing to the ¾-inch pin as a basis, the bearings to the ⅝-inch pins were determined by angular measurement.

The corner falls in the gravel driveway between storage buildings.

July 14, 1977

R. Roberts

E. Graham

Approved by:

Edward McGinty,

County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT


THIRD RE-ESTABLISHMENT

DLC64SE

GCDB 864110


Southeast corner of DLC #64 and the Northeast corner of DLC No. 65, Township 38 South, Range 1 West, W.M.

Found the 2½ ins. diam. brass cap marked;



13 ins. deep.

Over found monument, set a 1x12 ins. galvanized iron pipe with 2 1/2 ins. diam. brass cap marked;



Cemented in top flush with pavement.

From which Second Re-establishment, dated 1977, references found;

- Lead and tack located in cement threshold of doorway to unit #95 and 3.5 ft. East of the southwest corner of building, brs. record N27°00'00"W, 68.29 ft. Record distance 68.28 ft.
- Lead and tack located in cement threshold of doorway to unit #57 and 4.2 ft. East of the southwest corner of building, brs. N73°30'19"E, 12.21 ft. Record N68°E, 12.26 ft.

Set new references;

- 1 in. diam. alloy cap in drill hole in top of short piece of curbing, 2 ft. Westerly from the East end of said curbing brs. N52°24'14"W, 41.81 ft.
- 5/8 x 24 ins. rebar with aluminum cap (cap beat up but legible) marked

JACKSON COUNTY
●
SURVEYOR

Flush with ground in cinder landscape rock at South end of paving, bears S34°59'45"E, 130.15 ft.

Corner is located in paved area between storage buildings East of Unit 170 and West of Unit 57.

July 27, 2011

S. Beecher

S. Fein

Kerry K. Bradshaw

County Surveyor

P. - 3

Series II Book I