

FIRST RE-ESTABLISHMENT SPECIAL CORNER

DLC64SW

GCDB 863150

Southwest corner of Donation Land Claim No. 64, located in Section 26, Township 38 South, Range 1 West, W.M.

Utilizing evidence stated below and detailed on Survey No. 11287, set a 1x36-inch Galvanized iron pipe, 36 inches in the ground in concrete, over the top of a 3/4 inches outside diameter iron pipe found 13 inches below the surface of Wagner Creek Road.

In the top of the set pipe, set in concrete, a 2½-inch diameter brass cap marked:

T38S R1W
+
CS
1988

Take references as follows:

- A 5/8-inch diameter rebar with yellow plastic cap marked "Hardey LS 1990", found 16 inches deep at the Southwest corner of Lot 7, Taylor Subdivision, bears S44°15'27"E, 43.95 feet.
- A 2-inch diameter metal corner post at the Southeast corner of the chain link fence around the front yard at 518 Wagner Creek Road bears S83°15'19"W, 22.60 feet.
- The center of an unscribed Mimosa, 9-inch diameter, bears N50°13'47"W, 35.32 feet.

Corner lies about 0.5 feet West of the painted centerline of Wagner Creek Road.

See Job File 88-57.

August 15, 1988
D. Edwards, Tech.
T. Newcomb, Tech.

Edward McGinty
County Surveyor

P. -319