

FIRST RE-ESTABLISHMENT

DLC65SE

GCDB 865120

Southeast corner of DLC #65, Township 38 South, Range 1 West, W.M.

Found no evidence of the original corner.

At a point 1101.2 feet East from the Northeast corner of DLC #67, which record was reported on an old property survey by C.F. Rhodes, Civil Engineer in 1912, set a 1½" x 36" galvanized iron pipe with top flush with the ground for corner.

From which:

- An 8" Black Oak, scribed CS-BT bears N64°W, 73.2 feet to the face of the upper blaze
- A 12" Black Oak, scribed CS-BT bears N2°E, 21.8 feet to the face of the lower blaze.

April 29, 1961
L. D. Pinkham
C.L. Birk

Approved by:
M. E. Boyden,
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC65SE

Southeast corner of Donation Land Claim No. 65, Township 38 South, Range 1 West, W.M.

Found, 8 inches below and 18 inches North of the south edge of asphalt surface of Quail Run Road, near driveway to residence No. 2775, unrecorded brass cap:

SE | DLC
Cor. | 65
C.S.
1972

To perpetuate this position directly over said monument, set brass cap in concrete flush with the surface of road, marked:

SE | DLC
Cor. | 65
C.S.
1980

Reference trees marked and recorded on first renewal, in 1961 found as follows:

- Black oak, 15-inch diameter, with healed blazes, bears N2°E, 22.6 feet to center of tree at lower blaze. Record: 21.8 feet.
- The Southeast branch, 11-inch diameter, of a triple Black Oak, containing scribe marks in partially exposed upper face, bears N64°W, 73.44 feet to center of tree at upper blaze. Record: 73.2 feet.

Set rebars, 5/8-inch diameter, 30 inches long, with yellow plastic caps marked "JACKSON C.S." flush with the ground on East-West fence line:

- S38°06'E, 25.16 feet.
- S43°57'W, 36.70 feet.

December 16, 1980
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19½°
P. -232