

FIRST RE-ESTABLISHMENT

DLC65SSW

GCDB 865110

Southeast corner of DLC #66, located in Section 35, Township 38 South, Range 1 West, W.M.
(Also Southerly Southwest DLC #65)

Found 4 inches deep, the ¾-inch diameter, 24-inch long iron pipe recorded as marking the corner on Survey No. 4525.

Replaced the above, with a galvanized iron pipe, 1-inch diameter, 36 inches long, set 32 inches in the ground with a 2½-inch diameter bronze cap marked:

"JACKSON COUNTY 1981"
T38S R1W
SE
66
DLC

Deposited found pipe alongside corner and set new references:

Rebars, 5/8-inch diameter, 30 inches long, flush with the surface of the ground, with yellow plastic cap marked "Jackson C.S." on East-West fence line bears:

- S89°12'E, 27.37 feet.
- N89°12'W, 21.40 feet.

Corner lies on East-West fence line, about 4 feet, N67°E, of Power Pole No. D-8669.

January 19, 1981
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19½°
P. -12