

FIRST RE-ESTABLISHMENT

DLC67SSE

GCDB 513100

South Southeast corner to DLC #67, Township 38 South, Range 1 West.

Found the remains of Black Oak stump the BT to the Northwest said BT was identified by Mr. Kerby, an old settler.

- Also found the remains of pine roots to Southeast which agree with the official government record.
- Also found the ½" iron pipe for road center as reported by the County 1910 road survey as being 20 feet west of said DLC corner.

From which evidence:

- Set a 1½"x36" galvanized iron pipe 36" in the ground for corner;
- Set a ¾"x36" galvanized iron pipe which bears North 50.0 feet,
- The Southeast corner of a wood frame garage bears S3½°W, 21.35 feet,
- A ½"x18" iron pipe, the old road center, bears West 20.0 feet,
- Scribe a 5" Black Oak CS-BT which bears N82½°W, 123.2 feet.

February 23, 1946

C. Z. Boyden

C. W. Bentley

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC67SSE

GCDB 513100

South Southeast corner DLC No. 67, Township 38 South, Range 1 West, W.M. $V=20^\circ$

Found $\frac{3}{4}$ -inch x 30-inch I. Pipe set for P.I. 737, 24.2 per Reg. Survey No. 2696.

Replaced said pipe with a 1 x 36-inch G.I. pipe with $2\frac{1}{2}$ -inch bronze disc 9 inches deep, as witness to SSE Cor. DLC 67, marked:

Witness Cor.
T38S R1W
Jackson County 1973

Found a P-K nail at top of irrigation box at location of DLC #67, Township 38 South, Range 1 West.

From corner point, a $\frac{1}{2}$ -inch pipe, embedded in concrete, exposed 4 inches is located 0.10 feet North and 0.07 feet East, a found $\frac{5}{8}$ inches I. pin bears, $N1^\circ09'45''W$, 49.92 feet, 12 inches below surface.

- Set concrete nail in SW Corner of irrigation box, bears $S89^\circ19'50''E$, 23.06 feet.
- SE Corner wood frame garage, bears $S4^\circ34'10''W$, 21.13 feet.
- No evidence of the 5-inch Black Oak described in the February 23, 1946, Re-establishment.

January 30, 1973
B. Malotte
R. Frost

Approved by:
Edward McGinty,
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC67SSE

GCDB 513100

Witness corner to South Southeast corner of DLC #67, Township 38 South, Range 1 West, W.M.

Found 24 inches deep, the 2½-inch diameter brass cap marked:

Witness Cor.
T38S R1W
+
Jackson County 1973

Atop a 1-inch diameter, galvanized iron pipe, as recorded on Second Re-establishment in 1973.

References reported in 1973 found as follows:

- Iron pipe, ½-inch diameter, bears S89°39'44"E, 20.03 feet.
- Smooth iron pin, 5/8-inch diameter, found 1 foot deep, bears N21°30'58"E, 53.37 feet.
- P-K nail reported on Survey No. 5248 dated 1973 bears S89°19'50"E, 19.96 feet.

Set new references: 5/8 x 24-inch rebars flush, with Jackson County metal caps br:

- S05°30'19"W, 20.86 feet, located 2 feet west of east (6x8 ins.) wood gate post.
- S45°30'15"W, 29.24 feet, located 2 feet east of west (10x10 ins.) wood gate post.
- N72°16'19"W, 69.83 feet, located 4 feet N10°W, of the outlet end of an 18-inch diameter, c.m.p.

Also exposed the 1½-inch diameter iron pipe, noted on Survey Nos. 2696 and 2750. This pipe was reportedly set on the First Re-establishment in 1946. The pipe projects down from the bottom of the remains of partially destroyed concrete irrigation gate, which measurements indicated has been disturbed.

Set hub tack in lead atop the concrete "gate" at record position of the SSE Corner of DLC #67, which bears S89°19'50"E, 20.00 feet.

From the witness corner the southeast corner of Section 34 bears N89°19'50"W, 332.70 feet.

Note: The witness corner position is identical with 1910 Road Survey, STA. 737+24.2, per A. T. Brown, (page 79).

SEE project File No. 96-14

June 13, 1996
R. Frost, Tech.
T. Newcomb, Tech.

Roger Roberts
County Surveyor