

FIRST RE-ESTABLISHMENT

DLC67SW

GCDB 447100

Southwest corner of DLC #67, Township 38 South, Range 1 West, W.M.

Found corner marked by a stake attached to the lower wire of a woven picket fence with a staple, from which the original 20" White Oak stump S15°E, 80 lks, and the stump of the original 3" Plum tree N75°E, 5 lks.

Drove an iron pin (window weight) in place of the stake and left the stake attached to the fence.

I then blazed a 14" White Oak in two places, and marked the upper blaze C 67 CS and the lower BT which tree bears East 48.4 feet. Also drove two hubs flush with the ground, one bears East 15 feet and one West 15 feet.

February 3, 1913
A.T. Brown,
Deputy County Surveyor

C.D. Runyon, Chainman
M. B. Kellogg, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC67SW

GCDB 447100

Southwest corner to DLC No. 67, located in Section 34, Township 38 South, Range 1 West, W.M.

Found 8 inches deep, the 1½-inch diameter iron pipe set on Survey No. 2750 in 1964. Said pipe recorded as replacing the (window weight) monument set on First Re-establishment in 1913.

In the top of found pipe, in cement, set a 2½-inch diameter brass cap marked:

T38S R1W
DLC SW
67
C.S.
1984

References; ¾-inch diameter iron pipes, set on above noted survey, on East-West fence line bears:

- ▶ S51°19'E, 15.78 feet (projects 3 inches). Record: S50°E, 15.80 feet.
- ▶ S48°47'E, 14.73 feet (projects 2 inches). Record: S50°W, 14.76 feet.

A found 5/8-inch diameter iron pin with plastic cap (Reference Survey 9091) bears S82°47'E, 82.85 feet.

The (top) Southeast corner of the concrete foundation of an equipment shed, bears N4°50'E, 76.76 feet.

Corner lies 9.3 feet North of East-West fence line.

October 24, 1984
E. McGinty
R. Frost

Edward McGinty
County Surveyor

P.127-128

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT


THIRD RE-ESTABLISHMENT

DLC67SW

GCDB 447100

Southwest corner to DLC No. 67, located in Section 34, Township 38 South, Range 1 West, W.M.

Found the 2½ ins. diam. brass cap marked;



Set on the Second Re-establishment dated 1984, 6 inches deep.

References recorded on the Second Re-establishment found;

- ¾ ins. diam iron pipe protruding 3 ins. above ground, located on the North side of an East-West line, bears record S51°19'E, 15.78 ft. Record 15.80 ft.
- ¾ ins. diam iron pipe protruding 3 ins. above ground, located on the North side of an East-West line, bears S48°47'W, 14.76 ft. Bearing on Second re-establishment is in error, field notes from 1984 show a Southwest bearing.
- ⅝ ins. diam. iron pin with plastic cap marked 'McGinty LS301' protruding 5 ins. above ground, located at the North end of a white vinyl fence, bears record S82°47'E, 82.83 ft. Record distance 82.85 ft.
- The Southeast corner of equipment shed is not accessible due to fencing and is behind 6 ins. diam. Black Oak.

Corner is located 9 feet North of an East-West fence and 6 feet South of the South edge of graveled driveway.

September 15, 2010
S. Beecher

Kerry K. Bradshaw
County Surveyor

P. - 48
Series II Book I