

FIRST RE-ESTABLISHMENT

DLC78SW

GCDB 870170

Southwest corner of DLC No. 78 (abandoned), located in Section 24, Township 38 South, Range 1 West, W.M.

Found, 12 inches deep, at the corner, the 5/8-inch diameter rebar (with bent top) recorded on Survey No. 4673 in 1971.

Straighten and drive over said rebar a 1 x 36-inch G.I. pipe, flush with the ground, with 2-inch diameter steel cap marked:

T38S	R1W
CS	SW
	DLC
	78
	1980

- The single remaining bearing tree recorded by S. Truax in 1855, now a Black Oak stob, 23-inch diameter, with axed and/or rotted out faces, bears Record: N84°E, 204.6 feet to estimated face.
- The (brass cap) Northeast corner of DLC No. 70, for re-establishment, bears N0°17'50"E, 473.48 feet. Basis of bearing survey No. 4673.

New references:

- 5/8 x 30-inch rebar, projecting 3 inches in ring of stone with yellow plastic cap, marked: "Jackson C.S." located 1 foot east of fence electric line. Course: N45°E bears N0°17'50"E, 14.05 feet.
- 5/8 x 30-inch rebar, flush, with yellow plastic cap marked: "Jackson C.S.", located 0.5 feet north of east-west cyclone fence line, bears S0°17'50"W, 68.35 feet.

August 7, 1980
R. Frost
J. Gallegos
D. Danielsen

Edward McGinty
County Surveyor

P. -170