

## FIRST RE-ESTABLISHMENT

DLC83SE

GCDB 838130

Southeast corner of DLC #83, Township 38 South, Range 1 West, W.M.

Found the original witness tree to the Southeast, a 14" White Oak which bears S46°E, 44 links from the corner.

Set ½" gas pipe for corner and from this point turned off the bearings and distances given in the field notes for this corner and N61½°W, 114 links found the stump of a White Oak and S66°W, 207 links remains of a White Oak tree.

Set two new witness trees as follows:

- A 7-inch White Oak scribed C 83 CS on the upper and BT on the lower blaze, bears N34°W, 106.0 feet.
- An 8-inch White Oak scribed C 83 S 3 T38S R1W on the upper and BT on the lower blaze, bears N73½°E, 121.7 feet.

April 2, 1914  
A. T. Brown,  
Deputy County Surveyor  
H. Ling, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

DLC83SE

GCDB 838130

Southeast corner of DLC #83, Township 38 South, Range 1 West, W.M.

Found the ½" pipe for corner, also the original BT to the Southeast and the NE BT as reported by County Surveyor A. T. Brown in 1914.

Set a 1" x 35" iron pin 35" in the ground for corner at the exact location of the said ½" pipe,

- The face of the original BT, now a 22" White Oak bears S45°E, 28.5 feet,
- The re-established Northeast BT now a 10" White Oak with scribe visible bears N73½°E, 121.7 feet.
- A new BT, an 8" White Oak scribed CS-BT bears N31½°W, 114.0 feet,
- A new BT a 12" White Oak scribed CS-BT bears S6°W, 58.0 feet.

February 2, 1954  
C. Z. Boyden  
L. D. Pinkham  
M. E. Boyden

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT**

**DLC83SE**

**GCDB 838130**

Southeast corner Donation Land Claim No. 83, Township 38 South, Range 1 West, W.M.

Found the 1" iron pin set for corner on the Second Re-establishment on February 2, 1954.  
Replaced said 1" pin with a 3" bronze disk set in a concrete monument, stamped:

T38S R1W  
DLC | SE  
Cor. | 83  
-----  
C.S.  
1971

From which:

- The original bearing tree, now a sawed off stump, bears S45°E, 28.5 feet to the face;
- A 14" White Oak bears N72°55'E, 122.04 feet to center of the tree at the lower blaze. (1954 Record: 10" White Oak, N73½°E, 121.7 feet);
- An 18" White Oak bears S5°35'W, 58.25 feet to center of the tree at the lower blaze. (1954 Record: 12" White Oak, S6°W, 58.0 feet);
- A 12" White Oak, the Southerly of twin trunks, bears N32°01'W, 114.24 feet to center of the trunk at the lower blaze. (1954 Record: 8" White Oak, N31½°W, 114.0 feet).

April 26, 1972  
Lloyd Shreeve  
Ray Webber

Approved By:  
Mark E. Boyden  
County Surveyor

**SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT**

## FOURTH RE-ESTABLISHMENT

DLC83SE

GCDB 838130

Southeast corner to DLC No. 83, located in Section 3, Township 38 South, Range 1 West, W.M.

At the corner, found 1-inch deep, the brass cap set and described on Third Re-establishment dated 1972.

It being not practical to occupy corner as it and all bearing trees reported in 1972, (excepting the Northeast) are enclosed in dense blackberries; set a temporary point toward and on line with the Northeast (N72°55'E) bearing tree, 25.65 feet from the corner.

From said temporary point, the Northeast bearing tree, a White Oak, 14-inch diameter, axed into and found to be rotted and termite infested, bears N72°55'E, 96.80 feet to center of tree near base. Visibility to the Southwest and Northwest bearing trees, reported on Third Re-establishment, is obstructed.

- The Southwest being a 15-inch diameter White Oak with healed blaze, located 5.5 feet West of North-South bearing fence line.
- The Northwest is a double White Oak, the South branch, now 12-inch diameter, contains scribe "T" in partially opened lower face.

From this point a new bearing tree:

- Black Oak, 12-inch diameter, scribed "CS" "BT" bears N82°35'E, 65.19 feet to center.

From the preceding indirect measurements:

- The aforementioned Northeast bearing tree is determined to bear, from the (brass cap) DLC corner; N72°55'E, 122.45 feet to center near base. Record: 122.04 feet.
- The new (1985) bearing tree, bears N79°51'E, 90.58 feet to center of tree at lower blaze.

Corner lies 1.5 feet South of wood fence post on North-South fence line, about 50 feet South of the corner of North-South and West bearing fence lines and about 51 feet West of location marker on 12-inch diameter White Oak.

January 22, 1985  
E. McGinty  
R. Frost

Edward McGinty  
County Surveyor

P. 122-122A

SEE NEXT PAGE FOR FIFTH RE-ESTABLISHMENT

**FIFTH RE-ESTABLISHMENT**

**DLC83SE**

**GCDB 838130**

Southeast corner of Donation Land Claim No. 83, located in Section 3, Township 38 South, Range 1 West, W.M.

Found under north-south fence line, the 3-inch diameter brass cap marked:

T38S	R1W
DLC	SE
Cor.	83

C.S.  
1971

Set flush in concrete on Third Re-establishment.

The only reference visible from the corner,

- A double white oak, the southerly branch, 13-inch diameter, of which has healed upper blaze and scribe marks visible in partly exposed lower face, bears N32°01'W (basis of bearing) 114.18 feet to center of tree at said face.

Set new references: Rebars,  $\frac{5}{8}$  x 24 inches, flush with Jackson County metal caps, bears:

- N32°01'W, 111.80 feet.
- S59°00'01"W, 71.74 feet, located about 3 feet, N50°E of the middle of triple white oak.

Corner may be accessed from end of private drive off Marigold Lane (across from "Rancho done moving"). Follow gas line right-of-way north to corner.

May 6, 1996  
R. Frost, Tech.  
T. Newcomb, Tech.

Roger Roberts  
County Surveyor

P. -19