

FIRST RE-ESTABLISHMENT

DLC85ESE

GCDB 885150

East Southeast corner of DLC #85, Township 38 South, Range 1 West, W.M.

- Found the original Black Oak BT with scribe to the Southwest.
- Also the original BT to the Southeast is intact.

Set a 1½" x 36" galvanized iron pipe 34" in the ground for corner.

From which:

- The original BT now a 22" Black Oak with scribe legible bears S18°W, 88.4 feet.
- The original BT a 32" Black Oak intact, the center of which bears S59°E, 91.7 feet.
- Scribe a 12" White Oak CS-BT which bears N16°E, 64.0 feet a draw bears North 20 feet.

February 24, 1954

C. Z. Boyden

L. D. Pinkham

M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC85ESE

GCDB 885150

East Southeast corner DLC #85, Township 38 South, Range 1 West, W.M.

Found the 1½" galvanized iron pipe exposed 2" set for corner on the First Re-establishment on February 24, 1954.

At the same location, set a 3" brass disk in a 9" diameter concrete monument, stamped:

T38S R1W
ESE | DLC
Cor. | 85

C.S.
1972

From which:

- The original bearing tree, (now a Black Oak snag with partial scribe visible) bears S17°38'W, 89.0 feet to the center (original Record: 10" Black Oak, S18°W, 88.4 feet. 1954 Record: 22" Black Oak, S18°W, 88.4 feet.
- The original bearing tree, (now a 36" Black Oak snag in which I find a legible "T" scribe in the lower face) bears S9°00'E, 91.1 feet to the lower face. (Original Record: 12" Black Oak, S9°E, 91.1 feet. 1954 Record: 32" Black Oak, S59° (?) E, 91.7 to center);
- The bearing tree marked on the First Re-establishment now a 20" White Oak with two healed faces bears N15°48'E, 64.0 feet to center of the tree. (1954 Record: 12" White Oak, N16°E, 64.0 feet.)

Marked a new tree as follows:

- A 12" White Oak, scribed "CS-BT" bears S75°10'E, 29.4 feet to face of the lower blaze.

March 16, 1972
Lloyd Shreeve
Ray Webber

Approved by:
Mark E. Boyden
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC85ESE

GCDB 885150

East Southeast corner to DLC No. 85, located in Section 2, Township 38 South, Range 1 West, W.M.

Found the 3-inch diameter brass cap marked:

T38S R1W
ESE | DLC
Cor. | 85
C.S.
1972

Set in concrete, on the Second Re-establishment in 1972.

Original bearing trees, recorded by S. Truax in 1855 and reported in 1972, found as follows:

- Black Oak stump, 29-inch diameter containing scribe marks in exposed lower face, bears $S9^{\circ}E$, 91.22 feet to scribed face. Original Record: 91.08 feet.
- Black oak stob, 21-inch diameter containing scribe marks, bears as reported in 1972, $S17^{\circ}38'W$, 89.0 feet to center. Original Record: $S18^{\circ}W$, 88.44 feet.

Found bearing trees marked on First and Second re-establishment respectively:

- White Oak, now 17-inch diameter, with healed blazes, bears $N15^{\circ}48'E$, 63.8 feet to center of tree at lower blaze. Record (1972) 64.0 feet.
- White Oak, 11-inch diameter, with visible scribe marks in partially rehealed upper face, bears Record: $S75^{\circ}10'E$, 29.4 feet to estimated face of lower blaze. Re-measured 29.75 feet to center of tree at lower blaze.

Marked a new tree "CS" "BT":

- White Oak, 9-inch diameter, bears $N51^{\circ}44'W$, 79.16 feet to center of tree a lower blaze.

Corner lies 14 feet South of the center and at the top of the left bank of creek C. Northwest, about 101 feet South of East-West fence line and about 340 feet, $S68^{\circ}E$, of 9.5 feet square by 4 feet high concrete irrigation structure.

July 24, 1984
R. Frost
E. McGinty

Edward McGinty
County Surveyor

V = 18°
P. -93