


FIRST RE-ESTABLISHMENT

GCDB 100400

Section corner common to Sections 13 and 24 of Township 39 South, Range 2 East and Sections 18 and 19 of Township 39 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1967 and marked:



Single remaining original bearing tree recorded by Ives and Hyde of the GLO in 1854 found with a healed blaze and measured to center at base;

- P. pine now 46 ins. diam. brs. S7°E, 29.0 ft. record; 27.1 ft. to face.

Bearing trees recorded by the BLM in 1967 found with healed single blazes and measured to center at base;

- D. fir dead and down brs. record; N9°E, 21.1 ft. to remaining stob.
- P. pine now 26 ins. diam. with a partially healed blaze with illegible scribe brs. S45°W, 32.9 ft. record; 32.3 ft.

Marked new bearing trees 'CS''BT' and measured to center at lower blaze;

- W. fir 8 ins. diam. brs. N11°E, 33.0 ft.
- W. fir 8 ins. diam. brs. N43°W, 26.6 ft.

Corner lies approx. 900 ft. westerly from blocked spur road on east-west fence line on a 60% slope.

June 10, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -136

V. - 14°40'