

FIRST RE-ESTABLISHMENT

GCDB 240700

Quarter corner common to Section 32 of Township 38 South, and Section 5 of Township 39 South, Range 3 East, W.M.

Found at corner position , exposed 4 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1973, and marked:

T38SR3E
S32
—— ¼
S5
T39S
1973

Original Bearing trees recorded by Sewall Truax of the GLO in 1859 found with healed single blazes and measured to center at base;

- W. fir now 29 ins. diam. brs. record; N66½°E, 58.1 ft.
- South-east tree not search for

Bearing trees recorded by the BLM in 1973 found with healed single blazes and measured to center at base;

- W. fir now 26 ins. diam. brs. S5°E, 32.2 ft. record; 31.7 ft.
- W. fir now 40 ins. diam. brs. record; N89°E, 2.3 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 14 ins. diam. brs. N23°W, 13.0 ft.
- W. fir 6 ins. diam. brs. S58°W, 34.9 ft.

Corner lies approx. 200 ft. west of gravel road.

June 14, 2010

B. Beeman
H. Durkee

Kerry K. Bradshaw
Jackson County Surveyor

P. – 137
V. – 15°