

FIRST RE-ESTABLISHMENT

GCDB 300300

Section corner common to Sections 20, 21, 28 and 29, Township 39 South, Range 3 East, W.M.

Set a 1" x 36" galvanized iron pipe 18" in the ground with 2½" brass cap stamped:

T39S	R3E
20	21
<hr/>	
29	28
C.S.	
1967	

From which:

- The original bearing tree (now a 51" Yellow Pine), plainly scribed, bears N45½°E, 187.7 feet. Record: N44°E, 187.44 feet to the face of the upper blaze.
- The original bearing tree (now a 42" Yellow Pine) with healed blazes, bears S79¾°E, 190.8 feet. Record: S88½°E, 190.08 feet apparently in error by 10°, to center of tree.
- Found the stump hole of original bearing tree and a down badly decayed Yellow Pine snag to the Southwest, which checks the original record of South 34°W, 172.9 feet.
- The original bearing tree (now a 30" Yellow Pine) with the upper face chopped out, bears N83°W, 332.4 feet. Record: N83°00'W, 330.0 feet to the face of the upper blaze.

From said pipe corner, I establish a new bearing tree:

- A 14" Fir scribed CS-BT bears N11½°W, 150.1 feet to the face of the lower blaze.

No tree near in the Southwest quadrant.

May 23, 1967
F. A. Roberts
J. Huston

Approved by:
M. E. Boyden,
County Surveyor