

## FIRST RE-ESTABLISHMENT

GCDB 300540

Quarter corner common to Sections 8 and 9, Township 39 South, Range 3 East, W.M.

Found a 1" galvanized iron pipe with a 2½" bronze cap set for the corner by this office in 1971, but not recorded. Cap stamped:

T39S R3E  
¼ 8 | 9 Cor.  
C.S.  
1971

From which:

- The original bearing tree, now an 18" down Fir snag with scribe visible in upper face, bears N60°E, 23.1 feet to center of stump hole. Original Record: 10" Fir, N60°E, 22.4 feet.
- The original bearing tree, now a 30" Fir stump with "BT" scribe visible, bears N78½°W, 23.8 feet to face of lower blaze. Original Record: 16" Fir N81°W, 23.8 feet.

Found two bearing trees established on said 1971 re-establishment marked as follows:

- A 17" Fir scribed CS-BT bears N45°E, 36.5 feet to the face of the upper blaze.
- A 24" Fir scribed CS-BT bears N50¼°W, 76.6 feet to the face of the lower blaze.

June 8, 1972  
Lloyd Shreeve  
Ray Webber

Approved by:  
Gary Kaiser,  
Deputy County Surveyor