

FIRST RE-ESTABLISHMENT

GCDB 300600

Section corner common to Sections 4, 5, 8 and 9, Township 39 South, Range 3 East, W.M.

Found a stake and nail for corner, and replaced same with a 1" x 36" galvanized iron pipe, 30" in the ground, with a 2½" bronze cap stamped:

	T39S	R3E	
	5	4	
Sec.			Cor.
	8	9	
	C.S.		
	1972		

From which:

- The original bearing tree, now a 17" Fir snag with scribe visible, bears N51½°E, 36.1 feet to face of lower blaze. Record: 8" Fir, N51°E, 36.3 feet.
- The original bearing tree, now a 30" Fir with upper face open and scribe visible, bears S54½°E, 25.4 feet to face of upper blaze. Record: 8" Fir, S55°E, 26.4 feet.
- The original bearing tree, now a 24" Fir snag with scribe visible, bears S61¾°W, 20.0 feet to the center of the tree. Record: 12" Fir, S58°W, 19.8 feet.
- The original bearing tree, now a 33" Fir with scribe in upper blaze and chaining notch only in lower blaze, bears N58½°W, 5.6 feet to face of lower blaze. Record: 24" Fir, N71°W, 5.3 feet.

Marked new trees as follows:

- A 14" Fir scribed CS-BT bears, S37°W, 13.4 feet to face of the lower blaze.
- A 12" Fir scribed CS-BT bears, N22°E, 28.0 feet to face of the lower blaze.

June 9, 1972
Lloyd Shreeve
Ray Webber

Approved by:
Gary D. Kaiser,
Deputy County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 300600

Section corner common to Sections 4, 5, 8, and 9 of Township 39 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins., in a ring of stones, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on 1st re-establishment in 1972 and marked:

Jackson County Surveyor
T39S R3E
5 | 4
SEC —+— COR
8 | 9
C.S.
1972

Original bearing trees recorded by Sewall Truax of the GLO in 1859 found with partially healed single blazes and measured to center at base;

- Fir rotted remains brs. record ; N51½°E, 36.1 ft. to center of root depression
- Fir now 32 ins. diam. with scribe "T39SR3E S9" brs. S54½°E, 25.8 ft. record ; 25.4 ft to face.
- Fir snag with scribe "T39SR3E S8" brs. S60°W, 20.0 ft. record ; S61¾°W
- Fir dead, down, and rotted brs. N58½°W, 6.0 ft. record : 5.6 ft to face.

Bearing trees recorded on said 1st re-establishment in 1972 found with healed double blazes and measured to center at lower blaze;

- W. fir now 19 ins. diam. brs. S37°W, 13.9 ft. record ; 13.4 ft to face.
- W. fir now 19 ins. diam. brs. N22°E, 28.4 ft. record ; 28.0 ft to face.

Marked new bearing trees 'CS''BT' and measured to center at lower blaze;

- W. fir 9 ins. diam. brs. N19¾°W, 64.1 ft.

Corner lies approx. 70 ft. west of 4-wheel drive road.

June 15, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -138

V. - 16°