

## FIRST RE-ESTABLISHMENT

GCDB 340200

Quarter corner common to Sections 28 and 33, Township 39 South, Range 3 East, W.M.  $V = 20\frac{1}{2}^\circ$

Found, at the corner 2½-inch diameter Galvanized iron pipe stamped RCE 7282 on South side, projecting 12 inches in a mound of stone as set on Survey No. 5829-A in 1975.

Inside of which I found the copper nickel pipe set on Survey No. 1105 in 1958.

Over the copper nickel pipe, and inside of the 2½-inch Galvanized iron pipe, I drive a 1 x 36-inch Galvanized iron pipe 24 inches into ground, with a 2½-inch diameter bronze disc marked:

JACKSON COUNTY 1980  
T39S R3E  
28  
¼S —  
33

From which:

- I found the stump hole depression of original bearing tree recorded by E.T.T. Fisher in 1858, containing Fir fragments with old axe work, bears  $S61^\circ W$ , 337.0 feet. Record:  $S61^\circ W$ , 330.0 feet.

Reference trees recorded on Survey No. 1105, I found and took measurements to center at base:

- Sawed Pine stump, 22-inch diameter, bears  $N38^\circ E$ , 46.8 feet. Record:  $N38^\circ E$ , 46.2 feet.
- Sawed Fir stump, 24-inch diameter, bears  $S40^\circ E$ , 46.7 feet. Record:  $S40^\circ E$ , 40.2 feet.

I marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Douglas Fir, 12-inch diameter, bears  $N53^\circ E$ , 77.0 feet.
- Douglas Fir, 14-inch diameter, bears  $S64\frac{1}{2}^\circ W$ , 44.2 feet.

Corner of a South and West bearing fence lines, bears  $N81^\circ E$ , 4.60 feet.

May 1, 1980  
B. Malotte

Approved by: Edward McGinty  
County Surveyor